

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

ACCIDENT TIME REPORTED	16:29HRS	BUS REGISTRATION NUMBER	SMB1334R
ACCIDENT DATE	26-May-23	BUS TYPE (SD/DD)	SD
BUS CAPTAIN NAME	JIVARATHNAM A/L CHUMARAN	BUS ROUTE NO.	
THIRD PARTY CLAIM AGAINST	MSFCIL - GO AHEAD SPORE	BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	REAR LAMP STOP ASSY LED (RED) CM ✓	2	\$ 616.00
2	OS REAR SIGNAL LAMP CA ✓	1	\$ 413.60
1629.60		8% GST	\$ 82.37
		PARTS TOTAL COST	\$ 1,111.97

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • ITEM NOS 1 - 2	\$ 1,300.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- • OS REAR LAMP COVER • OS REAR DOME	\$ 1,950.00
SPRAY PAINTING :- • OS REAR LAMP COVER • OS REAR DOME	\$ 1,280.00
8% GST	\$ 362.40
LABOUR TOTAL COST	\$ 4,892.40

SPRAY PAINTING \$640 PER PANEL
LABOUR CHARGES \$650 PER DAY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

BUS TYPE (SD / DD) SD

LOSS OF USE COST

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

Ram
Hp 9w1w68
3 days
06/06/23 P1430

DATE IN	26-May-2023
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	5
\$1,500.00	

Resy after repair

1029.60
1975.00
3004.60

SUMMARY

SECTION NO.	COST
1	\$ 1,111.97
2	\$ 4,892.40
3	\$ 1,500.00
TOTAL	\$ 7,504.37