



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS3/HSB23005650/Uvp3m4

10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2 SINGAPORE
018983

Date: 14/06/2023

ATTN: LOH CYNTHIA

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SH 8631J	Veh. Inspected	SJQ 6784Z
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04MZG	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	05/06/2023

2. Vehicle Particulars & Condition


Make & Model	HONDA CIVIC (M)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMF45209S201134	Colour	SILVER
Odometer	241185 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.



5. General Information

Accident Date	02/06/2023	Inspect Date / Time	05/06/2023 (12:35 PM)
Survey held at	J & E AUTOMOBILE SERVICES 9002 TAMPINES INDUSTRIAL PARK A #01-44 SINGAPORE 528836		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------

Report Ref No. CS3/HSB23005650/Uvp3m4

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.