

(08/11/13) . wef

ASS. REC. BY: Marcus

REF:

CS/CT/230058-5/Unp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 52V 618IM

at Workshop m/s huot hock

of _____

Insured: SNB9310U

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$62k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 5677

Date: _____ Person Contacted: 1748 25114

Vehicle: IN / OUT

Veh No: 52V 618IM Yr Regn: 05/10/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Honda Shuttle C.C 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 109391 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 81200162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55-R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 02/06/23 D.O.I. 9/6/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 12k.

13/6/23 have video of folky 1/5 @ 3500 inform Bel (Red, \$ 6103.3, 63%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

➤ **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 567Z |
| Vehicle Details | |
| Vehicle No.: | SLV6181M |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 09 Jun 2023 |
| Vehicle Make: | HONDA |
| Vehicle Model: | SHUTTLE 1.5G CVT |
| Primary Colour: | Black |
| Manufacturing Year: | 2017 |
| Engine No.: | L15B5460198 |
| Chassis No.: | GK81200162 |
| Maximum Power Output: | 97.0 kW (130 bhp) |
| Open Market Value: | \$18,709.00 |
| Original Registration Date: | 05 Jan 2018 |
| First Registration Date: | 05 Jan 2018 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$8,709.00 4384 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 04 Jan 2028 |
| PARF Rebate Amount: | \$6,096.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 04 Jan 2028 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$41,617.00 |
| COE Rebate Amount: | \$19,018.00 |
| Total Rebate Amount: | \$25,114.00 |

The information contained herein is correct as at 09 Jun 2023

OK

Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**Low Interest Rate In-House Loan by GV Cars Financing**

\$0 Downpayment. Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate.
GV Automobile Centre StarAd



« Back (1 2) Next »

Sort by 20 results/page

21 vehicles



Shuttle








Any Category



Advanced Search



Search

| | Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|---|---|-------|-----------------|--------------|-------------|----------|------------|--------------|-------------------|
| Search Selection | Shuttle | | Any | Any | 2018 | Any | Any | Any | Available |
|  | Honda Shuttle Hybrid 1.5A G LED Honda Sensing | | \$76,888 | \$15,110 /yr | 11-May-2018 | 1,496 cc | 65,375 km | Stationwagon | Available |
| | Fuel Type: Petrol-Electric Honda shuttle Hybrid is a perfect family car with very low fc and huge cabin/boot space, this car is guaranteed a non phv unit with genu... | | | | | | | | PREMIUM AD |
| | Posted: 07-Jun-2023 | | | | | | | | |
|  | Honda Shuttle 1.5A G | | \$73,800 | \$14,730 /yr | 27-Feb-2018 | 1,496 cc | 49,861 km | Stationwagon | Available |
| | One Owner And Genuine Low Mileage. Pristine Condition. Low Fuel Consumption. Excellent Length And Spaces Interior. Unique And Bea... | | | | | | | | |
| | Posted: 06-Jun-2023 | | | | | | | | |
|  | Honda Shuttle Hybrid 1.5A | | \$85,800 | \$17,660 /yr | 26-Feb-2018 | 1,496 cc | 65,000 km | Stationwagon | Available |
| | Fuel Type: Petrol-Electric 1 owner, superb fuel consumption, phv welcome, warranty engine, gearbox, Hybrid battery till COE ends by in house workshop, buy wit... | | | | | | | | |
| | Car Times Automobile Pte Ltd | | | | | | | | |
| | Posted: 06-Jun-2023 | | | | | | | | |
|  | Honda Shuttle 1.5A G Honda Sensing | | \$74,888 | \$14,010 /yr | 21-Jun-2018 | 1,496 cc | 71,099 km | Stationwagon | Available |
| | New Stock arrival! One Owner Only. Confirmed Non PHV Unit. Honda Sensing Unit. New Car Condition Alike. Most Sought-after Japanes... | | | | | | | | PREMIUM AD |
| | Posted: 04-Jun-2023 | | | | | | | | |
|  | These 7-seater-looking cars only seat five Just as some mini MPVs surprise by squeezing seven into their tiny frames, the elongated designs of these cars suggest a third row - when they don't offer one. Read this article | | | | | | | | |
|  | Honda Shuttle 1.5A G | | \$73,800 | \$14,000 /yr | 17-May-2018 | 1,496 cc | 55,000 km | Stationwagon | Available |
| | Non PHV unit! 1 year warranty! 100% accident free, genuine low mileage! We provide comprehensive loan options to suit your needs! C... | | | | | | | | PREMIUM AD |
| | Posted: 03-Jun-2023 | | | | | | | | |
|  | Honda Shuttle Hybrid 1.5A | | \$78,888 | \$15,830 /yr | 05-Apr-2018 | 1,496 cc | 128,731 km | Stationwagon | Available |
| | Fuel Type: Petrol-Electric The Honda Shuttle Hybrid 1.5 is a compact hybrid station wagon that boasts a spacious and comfortable interior. It is equipped with a 1... | | | | | | | | PREMIUM AD |
| | Carro | | | | | | | | |
| | Posted: 03-Jun-2023 | | | | | | | | |

[Compare](#)



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO: 375654/00C

not follow
der
9/6/23
1/5 \$3500
w/ b. H. H. H.
4 days

| |
|-----------------------------|
| Carplate: SLV6181M |
| Chassis No: GK8-1200162 |
| Accident Date: 02/06/2023 |
| Make & Model: Honda Shuttle |

| No. | Item | Nett Price | ☑/☒ | Remarks |
|-----|--|-------------|---------|---------|
| 1 | Rear Bumper | \$ 1,250.10 | 936.00 | |
| 2 | Rear Bumper Side Retainer LH | \$ 30.90 | | 11 ✓ |
| 3 | Rear Bumper Side Retainer RH | \$ 30.90 | | 11 ✓ |
| 4 | Rear Bumper Reflector LH | \$ 59.10 | | 11 X |
| 5 | Rear Bumper Reflector RH | \$ 59.10 | | 11 X |
| 6 | Rear Bumper Reflector Moulding LH | \$ 112.10 | | 11 X |
| 7 | Rear Bumper Reflector Moulding RH | \$ 112.10 | | 11 X |
| 8 | Rear Bumper Towing Cover | \$ 28.10 | | 11 X |
| 9 | Rear End Panel | \$ 555.90 | | 11 ✓ |
| 10 | Rear End Panel Top Garnish | \$ 171.90 | | 11 X |
| 11 | Tailgate Weatherstrip | \$ 190.20 | | 11 X |
| 12 | Tailgate Lock Assembly | \$ 286.90 | 265.20 | 11 ✓ |
| 13 | Tailgate Trim Board | \$ 385.10 | | 11 X |
| 14 | Tailgate Lamp LH | \$ 322.70 | | 11 X |
| 15 | Tailgate Lamp RH | \$ 322.70 | | 11 X |
| 16 | Tailgate | \$ 1,425.90 | 1193.40 | 11 ✓ |
| 17 | Tailgate Logo " H " " | \$ 43.70 | | 11 X |
| 18 | Tailgate Logo " SHUTTLE " | \$ 48.90 | | 11 ✓ |
| 19 | Tailgate Windscreen Moulding | \$ 62.90 | | 11 ✓ |
| 20 | Spare Tyre Panel Compartment Board | \$ 385.90 | | 11 X |
| 21 | Spare Tyre Panel Compartment Board Cover | \$ 82.60 | | 11 X |
| 22 | Rear Bumper Reflector Foam Protector LH | \$ 75.20 | | 11 X |
| 23 | Rear Bumper Reflector Foam Protector RH | \$ 75.20 | | 11 X |
| 24 | Rear Antenna Sensor | \$ 135.20 | | 11 X |
| 25 | | | | |
| 26 | | | | |
| 27 | | | 202 | |
| 28 | | | | |
| 29 | | | | |
| 30 | | | | |
| 31 | | | | |
| 32 | | | | |
| 33 | | | | |

6253.3

| | Special Nett Items | Price | ✓/✗ | Remarks |
|-----|--|-----------|-----|-----------------|
| 1 | Rear Bumper Clips (1 Set) | \$ 30.00 | | RM ✓ |
| 2 | Rear End Panel Top Garnish Clips (1 Set) | \$ 30.00 | | RM ✗ |
| 3 | Tailgate Trim Board Clips (1 Set) | \$ 30.00 | | RM ✓ |
| 4 | Tailgate Windscreen Sealant | \$ 150.00 | | RM 40 |
| 5 | End Panel Sealant | \$ 120.00 | | RM 50 |
| 6 | Rear Reverse Sensor (1 Set) | \$ 280.00 | | me / bumper 200 |
| 7 | | | | |
| 8 | | | | |
| 9 | | | | |
| No. | All Necessary Work | Price | ✓/✗ | Remarks |
| 1 | To Carry Out Anti-rust Treatment | \$ 120.00 | | 30 |
| 2 | Rewiring to Facilitate Works | \$ 120.00 | | 20 |
| 3 | Transfer Tailgate Mechanism | \$ 120.00 | | 60 |
| 4 | Remove and Refit All Trims, Upholders, Garnish and All Necessary to Facilitate Repair Works | \$ 320.00 | | 80 |
| 5 | Remove and Reinstall Tailgate Windscreen | \$ 180.00 | | 120 |
| 6 | Remove and Install New Reverse Sensors | \$ 150.00 | | 50 |
| 7 | Labour to remove and replace damaged parts (Including refitting and repositioning of replaced parts) | \$ 900.00 | | 600 |
| 8 | Spray painting materials and respray of all affected and replaced parts necessary for paintwork | \$ 800.00 | | 600 |
| | Estimated No. of days for repairs and respray of all necessary | 4 Days | | |

S/N

9554-4

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9603-3

P-3124.1
202
2499.28
350
1560
4609.28
142
3527