

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23005688/Uqy3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	14/07/2023	
	ATTN: CHRYLLIS	QUAH		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNJ 9295M	Veh. Inspected	t	FBR 7875C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1226151-001	Excess (\$)		0.00	
	Assign From	JULIET KOH	Assign Date		06/06/2023	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX GDR155A	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SG4640LJ066519	Colour		RED	
	Odometer	85123 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	90-80-14	MAXXIS		7 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	100-80-14	MAXXIS		7 mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/05/2023	Inspection Dat	te	06/06/2023	
	Survey held at	EROFIA MOTOR TRADING PTE	LTD			
		1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					