



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23005769/Unp3e2 Date: 03/07/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 2911C	Veh. Inspected	SKA 3192Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2302272/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	07/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN SCIROCCO TSI (A)	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WVWZZZ13ZBV017900	Colour	PINK / WHITE	
Odometer	229413 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40Z R18	MICHELIN	6 mm	
L/H Front Tyre	225/40Z R18	MICHELIN	6 mm	
R/H Rear Tyre	225/40Z R18	MICHELIN	6 mm	
L/H Rear Tyre	225/40Z R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2023	Inspection Date	13/06/2023	
Survey held at	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	