



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LEXBUILD INTERNATIONAL PTE LTD 11 TUAS BAY CLOSE #04-01/02 WEST STARSINGAPORE 636996 ON BEHALF OF GO AHEAD SINGAPORE PTE LTD			Ref: CS/TP23005795/Tqp3e2 Date: 11/07/2023 Code: TP567	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	SG 6296L
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	YI XUAN	Assign Date	08/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	MAN A95	c.c	10518
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	WMAA95ZZ6LF014532	Colour	GREEN
	Odometer	142794 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
	L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S ROOFTOP. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/05/2023	Inspection Date	08/06/2023
	Survey held at	2 LOYANG WAY SINGAPORE 508776		
	Repairer	LEXBUILD INTERNATIONAL PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	