



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR23005812/Tnp3m4 Date: 02/08/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 916C	Veh. Inspected	SBS 6543L
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/06/23/2006	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	08/06/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ CITARO	c.c	6374
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WEB62808323126598	Colour	GREEN
Odometer	557047 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/80 R22.5	YOKOHAMA	8 mm
L/H Front Tyre	275/80 R22.5	YOKOHAMA	8 mm
R/H Rear Tyre	275/80 R22.5 (D)	YOKOHAMA	8/8 mm
L/H Rear Tyre	275/80 R22.5 (D)	YOKOHAMA	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/06/2023	Inspection Date	08/06/2023
Survey held at	BOXFRESH PTE LTD 7030 ANG MO KIO AVENUE 5 #06-49 NORTHSTAR @ AMK SINGAPORE 569880		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	