




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: OH VALE			Ref: CS3/HSB23005820/Rqp3e2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SH 8694C	Veh. Inspected	SLJ 4635Y	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S3M04N39	Excess (\$)	0.00	
Assign From	OH VALE	Assign Date	07/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA AXIO 1.5X	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NRE1610020102	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	WINDFORCE	6 mm	
L/H Front Tyre	175/65 R15	WINDFORCE	6 mm	
R/H Rear Tyre	175/65 R15	WINDFORCE	6 mm	
L/H Rear Tyre	175/65 R15	WINDFORCE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	06/06/2023	Inspect Date / Time	08/06/2023 ( 02:31 PM )	
Survey held at	LAY AUTO GARAGE PTE LTD 38 TOH GUAN ROAD EAST #01-56 ENTERPRISE HUB SINGAPORE 608581			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		

Report Ref No. CS3/HSB23005820/Rqp3e2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.