

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

28, Gul Drive, Singapore 629476 Tel : 63531131

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

OD CLAIM

To : Lonpac Insurance Bhd
Motor Claims Dept

Date : 07 Jun 2023

Dear Sirs :

Fax : 6896 8706

RE : ESTIMATE COST FOR MITSUBISHI FEB71 - YN9951B ALONG TEBAN GARDENS ON 15/05/2023

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front headlamp rh	1pc	\$ 330.00
4	Front side lamp rh	1pc	\$ 190.00
5	Front signal lamp rh	1pc	\$ 158.00
6	Front bumper	1pc	\$ 520.00
7	Front bumper bracket @\$140ea	2pcs	\$ 280.00
8	Front bumper side rh	1pc	\$ 210.00
10	Front chassis crossmember	1pc	\$ 400.00
11	Front step panel rh	1pc	\$ 270.00
12	Front step garnish rh	1pc	\$ 220.00
13	Front pillar rh	1pc	\$ 900.00
14	Front door rh	1pc	\$ 1,300.00
15	Front door rubber rh	1pc	\$ 220.00
16	Front door inner trim rh	1pc	\$ 620.00
17	Front door lower garnish	1pc	\$ 150.00
18	Front door hinge rh @\$110ea	2pcs	\$ 220.00
19	Front dashboard	1pc	\$ 1,550.00
20	Front dashboard lower cover	1pc	\$ 310.00
21	Front dashboard end cover rh	1pc	\$ 150.00
22	Air con blower	1pc	\$ 550.00
	Sum Carried Forward		\$ 8,548.00

	Sum Carried Forward		\$ 8,548.00
23	Air con heater	1pc	\$ 1,450.00
24	Front step wheel garnish	1pc	\$ 210.00
25	Front door glass rh	1pc	\$ 300.00
26	Front door reguator rh	1pc	\$ 500.00
27	Front pillar inner garnish rh	1pc	\$ 250.00
28	Front windscreen glass	1pc	\$ 500.00
29	Front windscteen rubber	1pc	\$ 150.00
30	Front wiper panel	1pc	\$ 280.00
31	Front panel	1pc	\$ 580.00
32	Fuso	1pc	\$ 115.00
33	Front wiper arm @\$115ea	2pcs	\$ 230.00
34	Front wiper blade @\$20ea	2pcs	\$ 40.00
35	Front wiper linkage	1pc	\$ 370.00
36	Front wiper motor	1pc	\$ 430.00
37	Front center grille	1pc	\$ 600.00
38	Front corner panel rh	1pc	\$ 320.00
39	Front mirror stay rh	1pc	\$ 290.00
40	Front mirror glass	1pc	\$ 80.00
			<u>\$ 15,243.00</u>
	Add 15%		<u>\$ 2,286.45</u>
			\$ 17,529.45
41	Front ERP bracket	1pc	\$ 15.00
42	Front number plate	1pc	\$ 30.00
	Sum Carried Forward		\$ 17,574.45

Sum Carried Forward \$ **17,574.45**

Labour Charge & Misc

Towing fee \$ 150.00

To remove, repair, replace & install front } \$ 2,500.00
damaged parts. }

To R & R wire harness \$ 180.00

To R & R front windscreen glass \$ 150.00

To remove & install door mechansim & } \$ 180.00
check for founction }

To R & R front cabin unit \$ 900.00

To R & R air con system } \$ 300.00
To refill & top up air con gas }

To R & R front dashboard \$ 350.00

To putty & spray painting. \$ 1,000.00

Total \$ 23,284.45

All prices quoted are subjected to GST.

This is a computer generated document. No signature is required.