



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: YON KAI JIE			Ref: CS3/INC22007815/Svp3m4-1 Date: 12/06/2023 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 732Z	Veh. Inspected	SMZ 988J
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1184228-004	Excess (\$)	0.00
	Assign From		Assign Date	03/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	BMW 316I	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WBA3A16030NS36620	Colour	SILVER
	Odometer	91413 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/40 ZR18	TOURADOR	5 mm
	L/H Front Tyre	235/40 ZR18	TOURADOR	5 mm
	R/H Rear Tyre	235/40 ZR18	TOURADOR	6 mm
	L/H Rear Tyre	235/40 ZR18	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/08/2022	Inspection Date	16/08/2022
	Survey held at	D'S GRAFFITI CONCEPTS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	