

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 8150Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SET FORK	NOT NECESSARY	450.00	-
1	FORK T-UNDER BRACKET	NOT NECESSARY	220.00	-
1	STEERING CONE	NOT NECESSARY	150.00	-
1	HANDLE BAR	BENT	250.00	175.00
1	HANDLE COVER 1	CUT	120.00	120.00
1	HANDLE COVER 2	CUT	120.00	80.00
1	MIRROR O/S	CUT	120.00	48.00
1	MIRROR BRACKET LEFT	NOT NECESSARY	100.00	-
1	BRAKE LEVER RIGHT	CUT	80.00	80.00
1	HANDLE BALANCER	CUT	50.00	35.00
1	FRONT DISC BRAKE	NOT NECESSARY	150.00	-
1	FRONT PANEL COVER	TWISTED	150.00	115.00
1	FRONT PANEL INNER COVER	CUT	120.00	120.00
1	FRONT FAIRING COVER RIGHT	CUT	220.00	155.00
1	FRONT FAIRING INNER COVER RIGHT	CUT	80.00	80.00
1	FRONT FOOTREST BOARD RIGHT	CUT	120.00	120.00
1	REAR FOOTREST RIGHT	SERVICEABLE	100.00	-
1	RADIATOR COVER	CUT	120.00	120.00
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	500.00	-
1	EXHAUST COVER	CUT	100.00	100.00
1	REAR BALANCER	CUT	280.00	280.00
1	REAR FAIRING COVER RIGHT	CUT	180.00	155.00
	LESS 10% DISCOUNT		-378.00	-178.30
			3,402.00	1,604.70
1	REAR BOX (SN)	CUT	450.00	380.00
	LESS 10% DISCOUNT		-45.00	-
			405.00	380.00
		l		

Report Ref No. CS/INC23005834/Uvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST PIPE.		500.00	300.00
			500.00	300.00
	GRAND TOTAL		4,307.00	2,284.70

RECOMMENDED COST OF LUMP SUM REPAIRS		1,800.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. CS/INC23005834/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser