

Shiau Chan (LKKAuto)

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Monday, 12 June 2023 12:24 PM
To: SUR
Cc: Lihong Lihong
Subject: SLQ8117M / DOA : 06.06.2023

Dear Sir / Madam,

We refer to the above matter.

Vehicle not economical for repair due to both front chassis having badly dented and the body structure seriously out of alignment.

Thank you



Freundliche Grüße / Best Regards

Carmen Lim

(M) +65 8799 0066

(E) carmen@esteemperf.com.sg

ESTEEM PERFORMANCE PTE LTD

HEADQUARTERS (SHOWROOM / WORKSHOP)

385 Sin Ming Drive, Singapore 575718


(T) +65 6753 2112 | (F) +65 6451 0394

BRANCH (WORKSHOP)

176 Sin Ming Drive, Sin Ming Autocare
#01-14/15/16, Singapore 575721

(T) +65 6484 1221 | (F) +65 6484 7829

www.esteemperformance.com



WE KEEP YOU DRIVING