

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No 199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH2000
Policy No:	MPC23P00079200	Date of Loss:	05/06/2023
Vehicle Reg. No.:	SFW8111T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHAI BIN SIEW		
Make/Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Vehicle Reg. Date:	20/03/2018
Vehicle Colour:	GREY		
Engine No:	MR20223439C	Chassis No:	JN1JANT32Z0010822
Odometer:	121351 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	10,296.00
Miscellaneous Items	225.00
Labour	2,390.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,911.00
+ GST 8.00% (S\$)	1,032.88
Nett Amount (S\$)	13,943.88

This claim is handled by: **TAN TING YI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Jun 2023)
Parts:	N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Wah Hong Motors & Credit Pte Ltd/SFW8111T/09/06/2023 10:37
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>bt</i>	0.00	0.00	*650.00 F
2	1		*Headlamp RH/LH@2*\$2200 <i>CM</i>	0.00	0.00	*4,400.00 F
3	1		*Front bumper <i>de</i>	0.00	0.00	*450.00 F
4	1		*Front bumper side retainer RH/LH@2*\$35 <i>u</i>	0.00	0.00	*70.00 F
5	1		*Center grille <i>over</i> ?	0.00	0.00	*320.00 F
6	1		*Center grille logo badge <i>u</i>	0.00	0.00	*350.00 F
7	1		*Center grille chrome <i>CM</i>	0.00	0.00	*180.00 F
8	1		*Carplate garnish <i>de</i>	0.00	0.00	*65.00 F
9	1		*Front bumper towing cover <i>de</i>	0.00	0.00	*25.00 F
10	1		*Front bumper lower grille?	0.00	0.00	*150.00 F
11	1		*Front bumper lower grille chrome?	0.00	0.00	*150.00 F
12	1		*Front bumper sponge?	0.00	0.00	*180.00 F
13	1		*Front bumper reinforcement?	0.00	0.00	*350.00 F
14	1		*Radiator air guide RH/LH@2*\$60?	0.00	0.00	*120.00 F
15	1		*Support top panel <i>req</i>	0.00	0.00	*200.00 F
16	1		*Support lower panel <i>X</i>	0.00	0.00	*250.00 F
17	1		*Condenser <i>X</i>	0.00	0.00	*700.00 F
18	1		*Radiator <i>X</i>	0.00	0.00	*750.00 F
19	1		*Front fender RH/LH (repair refer to labour)	0.00	0.00	*-F
20	1		*Chasis member RH/LH (repair refer to labour)	0.00	0.00	*-F

F=Franchise part.

Sub Total (\$\$)	9,360.00
+ Margin on L,N Items 10.00% (\$\$)	936.00
Total Parts (\$\$)	10,296.00

Wah Hong Motors & Credit Pte Ltd/SFW8111T/09/06/2023 10:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Bonnet insulator clip <i>an</i> ✓	30 35.00
2	1	Center grille clip <i>an</i> ✓	30 35.00
3	1	Coolant ?	? 50.00
4	1	Front bumper clip <i>an</i> ✓	30 35.00
5	1	Front carplate with holder <i>do</i> ✓	35.00
6	1	Radiator top garnish clip <i>an</i> ✓	30 35.00
Sub Total (S\$)			225.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	700 1,200.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	800 1,000.00
3	To perform anti-rust treatment on affected areas	New	30.00
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	40 60.00
5	Remove and replace/refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	New	? 100.00
Gross Labour Cost (S\$)			2,390.00

Wah Hong Motors & Credit Pte Ltd/SFW8111T/09/06/2023 10:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashid
the 20/100 68
6 days
45
27/06/23 PNR
EXCESS FBA
Revised
Reg after repair