

來發 (明記) 摩多有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No: EST0032266
 Pea Mui Kiang

Page: 1 of 3
 Your ref.: TP-GBC 6631A India
 Job No.: 73667
 Our ref.: 23.06.08
 Payment:
 Date: 9/6/2023

Attn

Vehicle No: SKA 928M
 Vehicle Model : Honda Vezel
 Accident on ...: 6/6/2023

*NOT AUTHORIZED
 11 May 8
 Recovery After Paim
 6 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Bonnet	857.20	20.00	<i>R1</i> 685.76 ✓
1.00	Pc	Bonnet hinge LH	50.50	20.00	<i>D11</i> 40.40 ✓
1.00	Pc	Bonnet hinge RH	50.50	20.00	40.40 ✓
1.00	Pc	Bonnet lock	109.30	20.00	<i>R1</i> 87.44 ✓
1.00	Pc	Front bumper	884.00	20.00	<i>T1</i> 707.20 ✓
1.00	Pc	Front bumper reinforcement	345.20	20.00	<i>R1</i> 276.16 ✓
1.00	Pc	Front bumper centre grille	87.10	20.00	<i>m11</i> 69.68 ✓
1.00	Pc	Front bumper side retainer LH	21.80	20.00	<i>CM</i> 17.44 ✓
1.00	Pc	Front bumper side retainer RH	21.80	20.00	<i>CM</i> 17.44 ✓
1.00	Pc	Front bumper lower	219.90	20.00	<i>B1</i> 175.92 ✓
1.00	Pc	Front bumper lower cover	107.80	20.00	86.24 ✓
25.00	Pcs	Front bumper clips	3.00	20.00	<i>nc</i> 60.00 ✓
1.00	Pc	Headlamp LH	1,967.50	20.00	<i>Ro</i> 1,574.00 ✓
1.00	Pc	Headlamp lower beam LH	37.30	20.00	<i>Ro</i> 29.84 ✓
1.00	Pc	Headlamp lower beam RH	37.30	20.00	<i>CM</i> 29.84 ✓
1.00	Pc	Front fog lamp LH	331.80	20.00	<i>CM</i> 265.44 ✓
1.00	Pc	Front fog lamp cover LH	41.90	20.00	<i>D1</i> 33.52 ✓
1.00	Pc	Front fender arch garnish LH	<i>my CM</i> 179.60	20.00	143.68 ✓

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
 还有先进的 SAICO Deluxe 喷漆烘炉。
 services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO ke oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No: EST0032266
 Pea Mui Kiang

Page: 2 of 3
 Your ref.: TP-GBC 6631A India
 Job No.: 73667
 Our ref: 23.06.08
 Payment
 Date: 9/6/2023

Attn

Vehicle No: SKA 928M
 Vehicle Model : Honda Vezel
 Accident on ...: 6/6/2023

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00	Pc	Front fender arch garnish RH	179.60	20.00	143.68	✓
1.00	Pc	Front support panel	544.30	20.00	435.44	✓
1.00	Pc	Front radiator grille	337.80	20.00	270.24	✓
1.00	Pc	Front radiator grille moulding	227.50	20.00	182.00	✓
1.00	Pc	Front radiator grille chrome moulding LH	68.00	20.00	54.40	✓
1.00	Pc	Front radiator grille chrome moulding RH	68.00	20.00	54.40	✓
1.00	Pc	Front radiator grille logo emblem	30.80	20.00	24.64	✓
1.00	Pc	Front radiator grille bracket, centre	43.50	20.00	34.80	✓
1.00	Pc	Front radiator grille bracket, LH	28.80	20.00	23.04	?
1.00	Pc	Front radiator grille bracket, RH	28.80	20.00	23.04	?
1.00	Pc	Radiator	1,335.40	20.00	1,068.32	?
1.00		Radiator coolant-4 litres	68.00	20.00	54.40	✓
1.00	Pc	Radiator air guide LH	47.00	20.00	37.60	✓
1.00	Pc	Radiator bracket bush LH (top)	24.30	20.00	19.44	?
1.00	Pc	Radiator bracket bush RH (top)	24.30	20.00	19.44	?
1.00	Pc	Radiator top cover	61.60	20.00	49.28	✓
10.00	Pcs	Radiator top cover clips	3.00	20.00	24.00	✓
1.00	Pc	Aircon condenser	683.90	20.00	547.12	✓
1.00	Pc	Aircon sensor holder	18.60	20.00	14.88	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
 还有先进的 SAICO Deluxe 喷漆烘炉。
 services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No: EST0032266
 Pea Mui Kiang

Page: 3 of 3
 Your ref.: TP-GBC 6631A India
 Job No.: 73667
 Our ref: 23.06.08
 Payment
 Date: 9/6/2023

Attn

Vehicle No: SKA 928M
 Vehicle Model : Honda Vezel
 Accident on ...: 6/6/2023

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Special nett item:			
1.00	Pc	Front number plate with casing	40.00		40.00 ✓
		Labour & Misc:			
1.00		Towing fee	70.00		70.00 601
1.00		To check/erase fault codes after repair	120.00		120.00 ?
1.00		To dismantle+renew aircon condenser and refill aircon gas	160.00		160.00 1001
1.00		To straighten front body including cutting and welding, to knock dents on front fender LH & RH and renew of parts	900.00		900.00 7001
1.00		To spray paint	1,200.00		1,200.00 10001
		Sub-Total			9,910.56
		GST 8.00%			792.84
		Total		S\$	10,703.40

司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
 还有先进的 SAICO Deluxe 喷漆烘炉。
 services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."