

# PORTDELGRO ENGINEERING PTE LTD

## AIR ESTIMATE\*

VEHICLE NO SHC8576S  
MAKE HYUNDAI  
MODEL IONIQ

DATE: 12.06.23  
MVA JUMANI  
DOA: 10.06.23

## INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING			\$451.25
SUB TOTAL				\$932.65
LESS 20%				\$186.53
DISCOUNTED TOTAL				\$746.12
SUB TOTAL				
Labour Charge				
PANEL BEATING				\$400.00
SPRAY PAINT				\$300.00
REMOVE/REFIX REVERSE SENSOR				\$50.00
TOTAL LABOUR				\$750.00
ESTIMATE TOTAL				\$1,496.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphi 97495749  
WP 12/6/23 440  
- 2 days  
Resy after repair  
Tanphi C/kharko.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: