

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

17/06/2023

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 08/06/2023

SKF

TP Budget Direct.
Veron.

JTHBW1GG902111388

Estimated repair cost for vehicle no: ~~SKF~~789X TOYOTA LEXUS ES300H CVT S/R

CHASSIS: JTHBW1GG902111388 (2015)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>deland</i>	\$1,015.90	\$1,015.90 ✓
2	1	REAR BUMPER REINFORCEMENT <i>dent</i>	\$570.90	\$570.90 ✓
3	1	REAR BUMPER SPONGE <i>cracked</i>	\$271.45	\$271.45 ✓
4	2	REAR BUMPER SIDE RETAINER <i>new</i>	\$173.40	\$346.80 X.
5	1	REAR BUMPER LOWER DIFFUSER <i>new</i>	\$781.10	\$781.10 X.
6	2	REAR BUMPER SIDE REFLECTOR <i>lit cracked</i>	\$182.55	\$182.55 91.
7	4	REAR BUMPER REVERSE SENSOR <i>2 piece deland</i>	\$295.30	\$1,181.20 590.60.
8	1	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	\$579.40	\$579.40 X.
9	1	REAR BOOTLID <i>new</i>	\$995.40	\$995.40 X.
10	1	REAR BOOTLID LOCK <i>new</i>	\$738.40	\$738.40 X.
11	1	REAR BOOTLID EMBLEM LOGO <i>new</i>	\$121.10	\$121.10 90
12	1	REAR BOOTLID EMBLEM LEXUS <i>new</i>	\$176.45	\$176.45 95
13	1	REAR BOOTLID EMBLEM ES300H <i>new</i>	\$181.90	\$181.90 102
14	1	REAR BOOTLID OUTER CHROME MOULDING <i>new</i>	\$227.40	\$227.40 X.
15	1	REAR END PANEL <i>new</i>	\$984.50	\$984.50 X.
16	1	REAR END PANEL TOP GARNISH <i>new</i>	\$584.90	\$584.90 X.
17	1	REAR END PANEL KEYLESS SENSOR <i>new</i>	\$364.20	\$364.20 X.
18	1	REAR WEATHER STRIPE <i>new</i>	\$358.40	\$358.40 X.

TOTAL : \$9,661.95

LESS 10% ~~\$2,415.49~~

SUB-TOTAL : ~~\$7,246.46~~

2826.85

2544.16

SFK789X TOYOTA LEXUS ES300H

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>Nw</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR END PANEL SEALANT	\$120.00	\$120.00 <i>+</i>
3	1	REAR END PANEL TOP GARNISH CLIPS	\$60.00	\$60.00 <i>+</i>
4	2	REAR BUMPER LOWER DIFFUSER CLIPS	\$80.00	\$80.00 <i>+</i>

30

TOTAL: \$340.00

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING

TOTAL PARTS: \$7,586.46

250
\$1,200.00
400 ~~\$1,000.00~~
30 ~~\$80.00~~
X ~~\$300.00~~
X ~~\$120.00~~

Subtotal :- \$2,700.00

Total:- \$10,286.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 13/06/23.

03 days.

total 325416

L/S 2.6K

2.6K