

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Sean Chun Yui, Chyi
Blk 460B Bukit Batok West Ave 9
#04-43
Singapore 652460

Vehicle No : SMZ 7154 C
Make : Kia Cerator
Year : 2019

Not Authorized
11/10/2020
Running After Parts
6 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear n/s door	1377
1 pc	Rear n/s door inner trim board	
1 pc	Rear n/s door glass regulator	
1 pc	Rear n/s door glass regulator motor	
1 pc	Rear n/s door inner lock	
1 pc	Rear n/s door rubber	
1 pc	Rear fender	
1 pc	Rear n/s fender air duct	
1 pc	Rear n/s fender inner shield	
1 pc	Rear n/s fender inner trim board	
1 pc	Rear windscreen moulding	
1 pc	Rear bumper	
1 pc	Rear n/s bumper side retainer	
1 pc	Rear n/s shock absorber	
1 pc	Rear n/s wheel hub	341
1 pc	Rear axle assy	
1 pc	N/S rocker panel garnish	691

R	\$1,385.00	✓
M	\$587.00	✓
M	\$255.00	✓
M	\$405.00	✓
M	\$287.00	X
M	\$225.00	50.00
R	\$1,183.00	✓
R	\$115.00	X
R	\$85.00	X
R	\$399.00	X
R	\$90.00	✓
R	\$688.00	X
R	\$85.00	X
R	\$205.00	X
R	\$389.00	✓
R	\$1,049.00	X
M	\$850.00	✓
	\$8,282.00	
Less 10 %	\$828.20	
	\$7,453.80	

S. Nett Item

1 pc	Rear n/s tyre rim
1 pc	Rear n/s door edge protector
1 pc	Rear windscreen sealant
30 pcs	Rear bumper clip

R	\$480.00	400.00
R	\$120.00	40.00
R	\$30.00	✓
\$2.50	\$75.00	X
	\$705.00	

Labour Charges

Remove/renew the above parts including knocking, cutting & welding.

balance c/f	\$1,500.00	800
	\$9,658.80	

MMZ 7154 C

balance b/f \$9,658.80

Labour Charges

To putty & spray paint on accident affected portion.	\$1,200.00	800
Check/reconnect wiring.	\$60.00	201
To spray anti rust on accident affected portion.	\$180.00	601
Remove/renew rear windscreen to facilitate repair.	\$120.00	✓
Remove/refit roof lining to facilitate repair.	\$180.00	100
Remove/refit fuel tank to facilitate repair.	\$120.00	601
Remove/renew rear undercarriages.	\$480.00	501
Check and realign wheel alignment	\$80.00	601
Remove/renew rear n/s door mechanism to new door	\$120.00	601
Total	\$12,198.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: