

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	14 Jun 2023 17:00	Clm Veh Model Changed	(204586) HONDA VEZEL 1.5 X CVT (A).	[R] Kiara Tan Yun Xi
2	14 Jun 2023 17:00	Clm Created	Reg No: SMH3634E. Policy No: MPC23A00014100. Acct Date: 2023/06/13. Claim Type: OD. Insurer: ECICS Limited (HQ). Works hop: Vin's Motor Pte Ltd (Sin Ming)	[R] Kiara Tan Yun Xi
3	14 Jun 2023 17:15	Clm Submitted	7583.00.	[R] Kiara Tan Yun Xi
4	15 Jun 2023 09:01	Clm Registration Modified	Excess: -> 0.00. Excess Waived: -> 750.00.	[I] Sharon Tan Chow Yen
5	15 Jun 2023 09:01	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: ECICS EXT ADJ - OD/TP. Suggested Adj. : LKK Auto Consultants Pte Ltd.	[I] Sharon Tan Chow Yen
6	15 Jun 2023 09:01	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/06/26	[I] Sharon Tan Chow Yen
7	15 Jun 2023 09:01	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Sharon Tan Chow Yen
8	15 Jun 2023 09:11	Assignment 1st Accessed		[A] NA MENG YAN
9	15 Jun 2023 09:19	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] NA MENG YAN
10	16 Jun 2023 11:53	Adj Rpt Initiated		[A] HUEY YON
11	16 Jun 2023 11:57	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2023/06/26	[A] HUEY YON
12	16 Jun 2023 11:57	Adj Mandate Request	Cur.Req:6602.00:damages consistent.repair cost economical. We have not authorise repair.	[A] HUEY YON
13	16 Jun 2023 15:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/06/26	[I] Sharon Tan Chow Yen
14	16 Jun 2023 15:39	Adj Mandate Set	Approved:6602.00.	[I] Sharon Tan Chow Yen

Date From   
 Date To   
 Audit Type 

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2980920	14 Jun 2023 17:00:33	OD/TP Case (Repairer)	Motor	Vin's Motor Pte Ltd	Vin's Motor Pte Ltd (Sin Ming)	SMH3634E		xx.xx
2980925	14 Jun 2023 17:04:41	CMF LITE (OD)	TrueSight-CMF	ECICS Limited (HQ)	ECICS Limited (HQ)	SMH3634E	KHONG LING YANG EDWIN	xx.xx
2981979	16 Jun 2023 11:53:06	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd	SMH3634E		11.00

