



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23006061/Kny3e2 Date: 19/07/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHF 155K	Veh. Inspected	SNH 363U	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/06/23/2036	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	15/06/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA JAZZ (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	JHMGR3830NS212768	Colour	METALLIC DARK BLUE	
Odometer	9078 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	YOKOHAMA	9 mm	
L/H Front Tyre	185/55 R16	YOKOHAMA	9 mm	
R/H Rear Tyre	185/55 R16	YOKOHAMA	9 mm	
L/H Rear Tyre	185/55 R16	YOKOHAMA	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	12/06/2023	Inspection Date	26/06/2023	
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	