COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHD6813R

MAKE

REG. 08.04.2016

MODEL

MERC E6

DATE 15.06.2023

CHIANG /INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER			\$1,510.00	
1	REAR BUMPER RETAINER			× \$115.00	
1	REAR DOOR PANEL LAY RH		16-	\$2,870.00	
1	REAR WHEEL RIM RH		del	\$1,250.00	
	SUB TOTAL		4/20	\$4,495.00	
	LESS 20%		3296	\$899.00	
) (14	\$3,596.00	
		1	at b		
1	DOOR COMFORT/MAXI STICKER	i I	80 mer-	\$80.00	
ł			12-22	\$80.00	
		K. 1	100 72		
	Labour Charge			. .	
	Panel Beating		6	\$900.00	
	Spray Painting Charge		100	\$900.00	
	Remove/Refix Upholstery rear			3120.00	
	Remove/Refix Door Parts		1660 6	\$180.00	
	TOTAL LABOUR		[660	\$2,400.00	
	ESTIMATE TOTAL		5028 Us\$ 4000 olfdays.	\$6,076.00	
	Taufum 97495749 wp, 15/6/23 e 430 pr 1/5 Resury affur reper funflin e /Manto.wn, Pays			ŀ	
1	Tauph 97495749		45\$4000		
	12 15/23047011		1 Halays.	l.	
	wp, 1) [0[2] & 13 p.		1 mg		
	2/5 Resury affer reper				
	southing Ist and win				
	T das c				
	Par				
	1				
	·				
	his is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
	be prepared after the vehicle is surveyed by a motor Support	epared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			
	and to the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer