

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHA1201E

MAKE/REG 25.05.2017

13.06.2023

MODEL TOYOTA PRIUS G4

CHIANG/INCOME

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER CLIPS		
1	REAR BUMPER		\$503.04
1	REAR BUMPER RETAINER LH		\$112.70
10	REAR BUMPER CLIPS	\$2.20	\$22.00
1	REAR BUMPER LOWER COVER		\$654.96
1	REAR BUMPER LOWER SIDE COVER LH		\$232.00
1	TAIL LAMP UPPER LH		\$557.90
1	TAIL LAMP LOWER LH		\$570.00
	<b>SUB TOTAL</b>	2652.60	\$2,652.60
	<b>25.00% DISCOUNTED TOTAL</b>	1989.45	\$663.15
			<b>\$1,989.45</b>
1	REAR REVERSE SENSOR		\$135.70
2	REAR FENDER ADVERTISEMENT LH/RH	200	\$200.00
			<b>\$322.13</b>
	<b>Labour Charge</b>		
	Panel Beating	350	\$900.00
	Spray Painting Charge	250	\$600.00
	Tuff Kote	630	\$60.00
	Remove and Refix Reverse Sensor	2819.45	\$60.00
	<b>TOTAL LABOUR</b>		<b>\$1,620.00</b>
	<b>ESTIMATE TOTAL</b>	4158.2250 2 days	<b>\$3,931.58</b>
A	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.		

Taifun 97445749  
 WP/ 14/6/23 2330p  
 L/S Masmy after repair  
 Taifun @ Kuantan

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: