Huey Yon (LKKAuto)

From: Huey Yon (LKKAuto)

Sent: Tuesday, 27 June 2023 11:25 AM

To: kennychan@alanutd.com

Cc:sur@lkkauto.com; janicechou@alanutd.comSubject:OD Case for YQ 1832Z DOA: 11/06/2023

Dear Sir/Mdm,

As instructed by our client, please proceed to repair the insured vehicle YQ 1832Z (Excess \$500/-).

Please take note that the rear canopy aluminium box only covered hood at \$2k.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards, Huey Yon | Case Handler LKK Auto Consultants

phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)