31/5/23 - Hb 01/6/23 - on site

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS

翠 NOTARY PUBLIC -公证官 玲 COMMISSIONER FOR OATHS- 宣誓官

律

師 CATHERINE C.L.LIM

馆 DIRECTOR

LL.B (HONS) SINGAPORE-法律系-律師 M.B.A. (BUSINESS LAW)-商业系-硕士 12 Eu Tong Sen Street
The Central (SOHO 2) #05-172
Singapore 059819
UEN No. 201310922K
Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation with limited liability

Our Ref: CL/230543/T/LBA.sg

29 May 2023

China Construction (South Pacific) Development Co. Pte Ltd

182 Cecil Street #31-01 Frasers Tower

Singapore 069547

WITHOUT PREJUDICE

via AR Registered

Dear Sir

ACCIDENT INVOLVING XD 4278J / LMM 962380X ON 19.04.2023 ALONG BUKIT TIMAH ROAD

We act for GOLDBELL LEASING PTE LTD, the owner of motor vehicle No. XD 4278J, which was involved in the above accident.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of motor vehicle No. LMM 962380X.

We quantify our client's claim as follows:-

1.	Cost of Repairs	\$ 5,250.00
2.	Loss of use (7 days x \$220)	1,540.00
3.	Survey fee	\$ 514.00
4.	Incidentals, transport & photocopying etc	\$ 54.00
5.	Cost contribution	\$ 1,080.00
		\$ 8,438.00

We enclose herewith photocopies of our client's accident report, repair bill, survey fee, survey report and colour photograph of our client's damaged vehicle for your immediate attention.

Please let us know within the next 14 days from the receipt of this letter, whether you are prepared to admit liability and revert with a settlement proposal, failing which our clients shall have no alternative but to commence legal proceedings against your insured.

Yoursyfaithfully

cc: clients

cc; chents

1 | Page C 1 / 2 3 0 5 4 3 - T / L B A SA1K234K0003-01 / Aspectus Consultancy Pte Ltd ENTRY DATE & TIME: 20/04/2023 16:50 (SGT) SUBMITTED BY: Weine Chieng VERSION: 2 (21/04/2023 10:14 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

20/04/2023 16:50 (SGT) **Actual Driver** 19/04/2023 14:40 (SGT) Bukit Timah Rd, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

XD4278J

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

Yes GOLDBELL LEASING PTE LTD 1XXXXX196N isaacngcl@gbl.com.sg (Phone) +65-90416329 (Office) +65-64942897

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC

Sh1eeka

Hino

Employment

No - Claiming third party Commercial vehicle Manual 12913

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

MS First Capital Insurance Ltd D22099240

DRIVER

Name of Driver Passport No/FIN Date Of Birth Occupation

LI YUSHUAI GXXXX334W 28/07/1980 Outdoor



Vehicle Colour Vehicle Category Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident No. Of Passenger (Including Driver)

NA / Unknown CHINA CONSTRUCTION (SOUTH PACIFIC) DEVELOPMENT CO

PTE TTD

(Phone) +65-85113957

Accident report SA1K234K0003

De	scribe Circumstances of the Accident						
ON 19/04/2023 AT ABOUT 1440HRS I WAS SATIONARY IN VEHICLE A(XD42 AT BUKIT TIMAH ROAD CONSTRUCTION SITE. WHILE VEHICLE B(LMM96238 IS UNLOADING FROM MY VEHICLE, VEHICLE B STARTED SWINGING AND WHIPPED MY REAR WINDSHIELD.							
	NO OTHER VEHICLE INVOLVED NOBODY WAS INJURED						

Declaration

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date& Time 20/04/2023 1340HRS

Witnessed by Reporting Centre Personnel DHIYAA















OTHER DOCUMENTS



10 Hougang Street 11 #14-29 The Minton Singapore 534080 Hand phone No. 96683949 Fax No. 63880908 Business Registration Nos. 53103119E

INVOICE

To

: Goldbell Leasing Pte Ltd

Date: 14th May 2023

c/o

: Liu's Brothers Auto Engineering Workshop

1 Kaki Bukit Avenue 6

Invoice No.: 10637/23

#01-01 Autobay @ Kaki Bukit

Singapore 417883

ITEM	PARTICULARS	AMOUNT
	Services rendered for automobile inspection report :	
	Survey fee :	
	(including transport charges and photographs)	
	Veh. No : XD4278J	
1	Model : Hino Sh1eeka	
	Our Ref : PA/MI/23/1009/3	
	Dollars :	
	Five hundred and fourteen only.	\$ 514.00

Perfect Automobile Appraisal Services

the

Our Ref: PA/MI/23/1009/3 Veh. No.: XD4278J

GENERAL DESCRIPTION OF DAMAGES:

At the time of inspection, we noted that this vehicle sustained damages on the cabin's rear portion.

For more details of the damages, please see schedule and photographs attached.

Attached fifty-four (54) photographs taken during our inspections.

CONCLUSIONS & RECOMMENDATIONS:

ORIGINAL QUOTATION : \$ 7,257.80

REVISED QUOTATION : \$ 5,250.00 (Lump Sum)

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment attached.

In normal circumstances, the repairs would take approximately five (5) days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** repair to the vehicle and the survey was conducted strictly on a 'WITHOUT PREJUDICE' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

The information contained in these documents is privileged and confidential and is for the exclusive use of the addressees designation. If you are not the addressee, any enclosure, reproduction, distributions or other dissemination or used of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for its return.

W/s Liu's Brothers Auto Engineering Workshop

Our Ref: PA/MI/23/1009/3

1 Kaki Bukit Avenue 6

Veh. No.: XD4278J

#01-01 Autobay @ Kaki Bukit

Singapore 417883

		COMMENTS/	ORIGINAL	REVISED	
	DESCRIPTIONS	CONDITION	QUOTATION	QUOTATION	١
OTY					

LABBOUR CHARGES

To putty and spray painting on front damaged portion including touch up paint on accident affected areas.

\$ 500.00 \$ 400.00

To apply rustproofing, reseal tuff-coating treatment to front replaced/ repaired parts and panels.

\$ 80.00 \$ 40.00 \$ 7,157.80 \$ 6,567.80

The repairer has agreed to undertake repairs on a contractual basis at **Lump Sum** \$ 5,250.00 corresponding to supply of parts, labour and spray painting charges.

CHUAH POH SIONG GARY

CAE, MIMI, AMSOE,


AMIRTE, AMSAE-AUS, MSAAA


Vehicle No: XD4278J




PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No: XD4278J













Date of Accident: 19 April 2023



Page 2 of 8

PERFECT AUTOMOBILE APPRAISAL SERVICES


Vehicle No XD4278J

















Page 4 of 8

PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No XD4278J

Re-inspection Photos
















Vehicle No XD4278J


















Page 8 of 8

PERFECT AUTOMOBILE APPRAISAL SERVICES

Vehicle No XD4278J

Re-inspection Photos





