

(08/11/13) Web

ASS. REC. BY: Borne

REF:

2004

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MYTo Inspect Vehicle No: SNF 6573Bat Workshop m/s BORNEof PANDORA CRESCENTInsured: LPC

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

136K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 65K

Veh No:

SNF 6573B

Yr Regn:

2022 / JunType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA SIENNA HYBRID ST c.c. 1497

Colour:

BLACK

A/C:

Insured / Std / NI / NA

Sp. Reading

80409

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

3TD 229H 330 L001013Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NIL / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/06/23

D.O.I.

13/06/23

Survey held at

BORNEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) \$ + RS. \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 13/06/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZZ9H330L001013	1NZ9398158	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR POLICY NO.:XB9047L ACC DATE:13/06/23 DRIVE IN:13/06/23 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				198.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)				X 200.00
5	L	BP-LPO SUPPLY REAR REGN PLATE (PO#)				X 80.00
6	L	BP-LPO SUPPLY PHV STICKER				20.80
7	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPARTMENT				594.00
8	B	BP-LAB2 REMOVE AND REPLACE TAILGATE GLASS				594.00
9	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				326 702.00
10	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				1584 4782.00
11	B	BP-RES2 RESPRAY ACC ACC AREA				132 3936.00
12	1	T52159-52978 COVER, RR BUMPER <i>repair</i>	1.00	431.30		431.30
13	2	T52161-16010 PIECE, RR BUMPER <i>repair</i>	10.00	5.70		57.00
14	3	T52155-52131 SUPPORT, RR BUMPER <i>?</i>	1.00	128.40		128.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925
	Document No. 0	
	Document Date 13/06/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZZ9H330L001013	1NZ9398158	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	4	T52156-52130 SUPPORT, RR BUMPER ?	1.00	128.40		128.40
16	5	T52575-52200 RETAINER, RR BUMPER X	1.00	95.40		95.40
17	6	T52576-52180 RETAINER, RR BUMPER X	1.00	95.40		95.40
18	7	T52591-52360 SEAL, RR BUMPER X	1.00	78.70		78.70
19	8	T52592-52350 SEAL, RR BUMPER X	1.00	78.70		78.70
20	9	T52151-52010 EXTENSION, RR BUMPER X	1.00	243.00		243.00
21	0	T52161-52170 EXTENSION, RR BUMPER X	1.00	165.20		165.20
22	1	T52162-52150 EXTENSION, RR BUMPER X	1.00	165.20		165.20
23	2	T58307-52670 PANEL SUB-ASSY, BODY X	1.00	588.10		588.10
24	3	T58302-52162 PANEL SUB-ASSY, LWR X	1.00	944.00		944.00
25	4	T64716-52180 C0 COVER, DECK TRIM, RR X	1.00	188.20		188.20
26	5	T64421-52100 C0 TRAY, LUGGAGE X	1.00	571.60		571.60
27	6	T58408-52100 C0 BOARD SUB-ASSY, X	1.00	357.90		357.90
28	7	T67005-52E50 PANEL SUB-ASSY, BACK X	1.00	1535.20		1535.20
29	8	T67881-52220 WEATHERSTRIP, BACK X	1.00	476.60		476.60
30	9	T67750-52100 C0 BOARD ASSY, BACK X	1.00	176.60		176.60
31	0	T68105-52660 GLASS SUB-ASSY, BACK X	1.00	1404.30		1404.30
32	1	T56117-64010 DAM, WINDOW GLASS X	1.00	66.30		66.30
33	2	T68950-0W840 STAY ASSY, BACK X	1.00	310.80		310.80
34	3	T68960-0W840 STAY ASSY, BACK X	1.00	310.80		310.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



ESTIMATE

Account Details		Account No.	Customer Details	
onpac Insurance Berhad 00 Beach Road 19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	M/S Grab Rentals Pte. Ltd	
		Document No.	3 Media Close	
		0	#01-03/06	
		Document Date	Singapore 138498	
		13/06/2023	Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZZ9H330L001013		1NZ9398158	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
35	4	T69350-52401 LOCK ASSY, BACK DOOR X	1.00	599.10		599.10
36	5	T69430-52050 STRIKER ASSY, BACK X	1.00	33.20		33.20
37	6	T76801-52411 C1 GARNISH SUB-ASSY, X	1.00	266.80		266.80
38	7	T75403-52010 EMBLEM SUB-ASSY, X	1.00	86.60		86.60
39	8	T75441-52170 PLATE, BACK DOOR X	1.00	66.60		66.60
40	9	T81551-52E30 LENS & BODY, RR X	1.00	479.80		479.80
41	0	T81561-52E30 LENS & BODY, RR X	1.00	479.80		479.80
42	1	T81581-52380 LENS & BODY, RR X	1.00	258.60		258.60
43	2	T81591-52380 LENS & BODY, RR X	1.00	258.60		258.60
44	3	T81270-0D120 LAMP ASSY, LICENSE X	1.00	84.20		84.20
45	4	T81910-52030 REFLECTOR ASSY, X	1.00	77.20		77.20
46	5	T81920-52030 REFLECTOR ASSY, X	1.00	77.20		77.20
47	6	SPC507-0D014 209 BACK SENSOR 209, BLACK MICA-X	1.00	172.40		172.40
48	7	T21000-20 SIKI 182010 SIKI TACK GO! (BLA X	1.00	108.00		108.00
49	8	T21000-22 SIKI 207. G+P ADHESIVE PRIMER X	1.00	200.00		200.00

For & on behalf of	Customer's Signature	Charge Summary	Total	23,310.00
Borneo Motors (Singapore) Pte Ltd			GST 8.00%	1,864.80
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Parts 11,845.20 Labour 11,364.00 Sublet 100.80 Lubrication/Fluid 0.00 Others 0.00	Less	0.00
Acknowledged by Repairer Signature: Date:			Amount Due	25,174.80

Customer Copy

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	200G
Vehicle No.:	SNF6573B
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID STANDARD (AUTO)
Primary Colour:	Black
Manufacturing Year:	2022
Engine No.:	1NZ9398158
Chassis No.:	JTDZZ9H330L001013
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$24,908.00
Original Registration Date:	15 Jun 2022
First Registration Date:	15 Jun 2022
Transfer Count:	0
Actual ARF Paid:	\$11,872.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2032
PARF Rebate Amount:	\$8,904.00
COE Expiry Date:	14 Jun 2032
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,699.00
COE Rebate Amount:	\$61,819.00
Total Rebate Amount:	\$70,723.00

The information contained herein is correct as at 15 Jun 2023

OK

Toyota Sienta 1.5A Standard

\$112,800 Instalment \$1,136/mth

PREMIUM AD

 Shortlist

 Loan Calculator



Overview Financial Photo Research

Depreciation	 \$14,280 / year
Reg. Date	24-Sep-2020 (7yrs 3mths 8days COE left)
Manufactured	 2019
Mileage	54,479 km (20k / year)
Transmission	Auto
Engine Cap	1,496 cc
Road Tax	 \$682 / year
Power	79.0 kW (105 bhp)
Curb Weight	 1,325 kg
COE	 \$37,766
OMV	 \$17,644