



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 13/06/2023	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZZ9H330L001013	1NZ9398158	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR POLICY NO.:XB9047L ACC DATE:13/06/23 DRIVE IN:13/06/23 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				198.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
5	L	BP-LPO SUPPLY REAR REGN PLATE (PO#)				80.00
6	L	BP-LPO SUPPLY PHV STICKER				20.80
7	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPARTMENT				594.00
8	B	BP-LAB2 REMOVE AND REPLACE TAILGATE GLASS				594.00
9	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				792.00
10	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				4752.00
11	B	BP-RES2 RESPRAY ACC ACC AREA				3936.00
12	1	T52159-52978 COVER, RR BUMPER	1.00	431.30		431.30
13	2	T52161-16010 PIECE, RR BUMPER	10.00	5.70		57.00
14	3	T52155-52131 SUPPORT, RR BUMPER	1.00	128.40		128.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 13/06/2023	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZZ9H330L001013	1NZ9398158	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	4	T52156-52130 SUPPORT, RR BUMPER	1.00	128.40		128.40
16	5	T52575-52200 RETAINER, RR BUMPER	1.00	95.40		95.40
17	6	T52576-52180 RETAINER, RR BUMPER	1.00	95.40		95.40
18	7	T52591-52360 SEAL, RR BUMPER	1.00	78.70		78.70
19	8	T52592-52350 SEAL, RR BUMPER	1.00	78.70		78.70
20	9	T52151-52010 EXTENSION, RR BUMPER	1.00	243.00		243.00
21	0	T52161-52170 EXTENSION, RR BUMPER	1.00	165.20		165.20
22	1	T52162-52150 EXTENSION, RR BUMPER	1.00	165.20		165.20
23	2	T58307-52670 PANEL SUB-ASSY, BODY	1.00	588.10		588.10
24	3	T58302-52162 PANEL SUB-ASSY, LWR	1.00	944.00		944.00
25	4	T64716-52180 C0 COVER, DECK TRIM, RR	1.00	188.20		188.20
26	5	T64421-52100 C0 TRAY, LUGGAGE	1.00	571.60		571.60
27	6	T58408-52100 C0 BOARD SUB-ASSY,	1.00	357.90		357.90
28	7	T67005-52E50 PANEL SUB-ASSY, BACK	1.00	1535.20		1535.20
29	8	T67881-52220 WEATHERSTRIP, BACK	1.00	476.60		476.60
30	9	T67750-52100 C0 BOARD ASSY, BACK	1.00	176.60		176.60
31	0	T68105-52660 GLASS SUB-ASSY, BACK	1.00	1404.30		1404.30
32	1	T56117-64010 DAM, WINDOW GLASS	1.00	66.30		66.30
33	2	T68950-0W840 STAY ASSY, BACK	1.00	310.80		310.80
34	3	T68960-0W840 STAY ASSY, BACK	1.00	310.80		310.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 13/06/2023	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZZ9H330L001013	1NZ9398158	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
35	4	T69350-52401 LOCK ASSY, BACK DOOR	1.00	599.10		599.10
36	5	T69430-52050 STRIKER ASSY, BACK	1.00	33.20		33.20
37	6	T76801-52411 C1 GARNISH SUB-ASSY,	1.00	266.80		266.80
38	7	T75403-52010 EMBLEM SUB-ASSY,	1.00	86.60		86.60
39	8	T75441-52170 PLATE, BACK DOOR	1.00	66.60		66.60
40	9	T81551-52E30 LENS & BODY, RR	1.00	479.80		479.80
41	0	T81561-52E30 LENS & BODY, RR	1.00	479.80		479.80
42	1	T81581-52380 LENS & BODY, RR	1.00	258.60		258.60
43	2	T81591-52380 LENS & BODY, RR	1.00	258.60		258.60
44	3	T81270-0D120 LAMP ASSY, LICENSE	1.00	84.20		84.20
45	4	T81910-52030 REFLECTOR ASSY,	1.00	77.20		77.20
46	5	T81920-52030 REFLECTOR ASSY,	1.00	77.20		77.20
47	6	SPC507-0D014 209 BACK SENSOR 209, BLACK MICA	1.00	172.40		172.40
48	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	1.00	108.00		108.00
49	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 23,310.00
	Please acknowledge receipt of vehicle	Parts 11,845.20 Labour 11,364.00 Sublet 100.80 Lubrication/Fluid 0.00 Others 0.00	GST 8.00% 1,864.80
			Less 0.00 Amount Due 25,174.80

Customer Copy