



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HL ASSURANCE PTE LTD
11 KEPPEL ROAD
#11-01 ABI PLAZASINGAPORE 089057

Ref: CS/HLA23006169/Avy3

Date: 19/06/2023

Code: HLA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 1823S	Veh. Inspected	SGA 1038Y
Policy No.	MP314836	Coverage (\$)	0.00
Claim No.	MPC04317	Excess (\$)	0.00
Assign From	ROMEO LYNN	Assign Date	19/06/2023

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/06/2023	Inspection Date	20/06/2023
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--