



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Ref: CS/EQI23006170/Tqy3

Date: 19/06/2023

Code: EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 1357L	Veh. Inspected	SLB 1357L
Policy No.		Coverage (\$)	0.00
Claim No.	DM23HO01280/JT	Excess (\$)	0.00
Assign From	JAIME TAY	Assign Date	19/06/2023

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/06/2023	Inspection Date	20/06/2023
Survey held at	EVEREST MOTOR GARAGE PTE LTD 25 KAKI BUKIT ROAD 4, #05-80, SYNERGY @ KB, SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--