



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 9010E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER RH FRONT WING MIRROR NECK (N)	MISSING	55.10	55.10
1	EMBLEM-SIDE FRONT DOOR RH (N)	NECESSARY	105.00	105.00
1	MIRROR ASSY-OUTER RH (N)	CRACKED	276.60	276.60
1	TAPE-FR DOOR SASH (N)	NECESSARY	29.00	29.00
1	TAPE-FR DOOR, RH (N)	NECESSARY	36.10	36.10
1	TAPE-FR DOOR, RH (N)	NECESSARY	32.60	32.60
1	DOOR-FRONT RH (N)	BENT	1,128.50	1,128.50
	LESS 20% DISCOUNT		-332.58	-332.58
			1,330.32	1,330.32
<u>SPECIAL NETT ITEMS</u>				
1	SEALANT RH FRONT 1/4 GLASS (SN)	NOT NECESSARY	48.00	-
1	RH FRONT 1/4 GLASS (SN)	NOT NECESSARY	454.30	-
1	SUNDRIES (SN)	NECESSARY	20.00	20.00
			522.30	20.00
<u>LABOUR</u>				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		100.00	100.00
	INSTALL ULTRAMAX SOLAR FILM - QUARTER GLASS RH FRONT.	NOT NECESSARY	50.00	-
	REPAIR AND RENEW RH FRONT DOOR AND RH WING MIRROR.		900.00	390.00
	S/PAINT RH FRONT DOOR AND RH WING MIRROR COVER.		750.00	350.00
	TRANSFER RH FRONT DOOR MECHNICAL PARTS TO NEW DOOR.		60.00	60.00
	RENEW RH WING MIRROR LED.		120.00	120.00
	RENEW RH FRONT 1/4 GLASS.	NOT NECESSARY	120.00	-
			2,220.00	1,020.00
GRAND TOTAL			4,072.62	2,370.32

Report Ref No. CS/SMR23006175/Rvy3e2



RECOMMENDED COST OF REPAIRS			2,370.32
------------------------------------	--	--	-----------------

Report Ref No. CS/SMR23006175/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.