



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR23006175/Rvy3e2 Date: 18/07/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SHD 6289D	<b>Veh. Inspected</b>	SNC 9010E
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	TAX/06/23/2040	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANA	<b>Assign Date</b>	19/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	NISSAN NOTE E-POWER 1.2 PRE	<b>c.c</b>	1198
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2021
<b>Chassis No.</b>	JN1FAAE13Z0900679	<b>Colour</b>	BLUE
<b>Odometer</b>	21479 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	185/60 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	185/60 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	185/60 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	185/60 R16	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.		
<b>5. General Information</b>			
<b>Accident Date</b>	15/06/2023	<b>Inspection Date</b>	21/06/2023
<b>Survey held at</b>	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		
<b>5a. Remarks</b>			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
<b>5b. Estimate Days of Repair</b>			
	ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>	