

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0179/2023  
DATE : 16-JUN-2023

MS FIRST CAPITAL INSURANCE LIMITED  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
S(068877)  
TEL : 65073848  
FAX :  
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR WEE SIOW WOON (RUAN SHAO'EN)  
ADDRESS : BLK 436C FERVALE ROAD  
#05-168  
S(793436)  
TELEPHONE NO : 97537899

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-SHD6289D  
VEHICLE NO : SNC9010E  
MODEL CODE : FDWARF9E13HDAY646Z  
MODEL/YEAR : NISSAN NOTE 1.2L E-POWER PREMIUM (I) MY2020  
ENGINE NO : HR12017512L  
CHASSIS NO : JN1FAAE13Z0900679  
MILEAGE : 1 KM  
DATE IN : 16/06/2023  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 15/06/2023

17/07/2023

Assun

LOU

#50X 03

= #150/

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNC9010E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	.00
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
3	SQG	INSTALL ULTRAMAX SOLAR FILM - QUARTER GLASS RH FRONT	50.00	.00
4	ZZ/001	REPAIR AND RENEW RH FRONT DOOR AND RH WING MIRROR	900.00	390.00
5	ZZ/002	S/PAINT RH FRONT DOOR AND RH WING MIRROR COVER	750.00	350.00
6	ZZ/003	TRANSFER RH FRONT DOOR MECHANICAL PARTS TO NEW DOOR	60.00	60.00
7	ZZ/004	RENEW RH WING MIRROR LED	120.00	120.00
8	ZZ/005	RENEW RH FRONT 1/4 GLASS	120.00	.00
TOTAL LABOUR CHARGES			2220.00	1020.00

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNC9010E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	COVER RH FRONT WING MIRROR NECK	96312-6XJ0A	55.10			OK
2	SEALANT RH FRONT 1/4 GLASS	SEALANT - 3			48.00	X
3	RH FRONT 1/4 GLASS	802A0-6XJ1A			454.30	X
4	EMBLEM-SIDE FRONT DOOR RH	63891-6XJ0A	105.00			OK
5	MIRROR ASSY-OUTER RH	96301-6XJ2A	276.60			OK
6	TAPE-FR DOOR SASH	80816-6XL0A	29.00			OK
7	TAPE-FR DOOR,RH	80812-6XL1A	36.10			OK
8	TAPE-FR DOOR,RH	80818-6XL0A	32.60			OK
9	DOOR-FRONT RH	H010M-6XJMA	1128.50			OK
10	SUNDRIES	NPN			20.00	OK
SUB TOTAL			1662.90	0.00	20.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			332.58	0.00	0.00	
GRAND TOTAL			1330.32	0.00	20.00	
OVERALL TOTAL			1350.32			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SNC9010E

-----

NETT ITEM	1662.90
LESS 20.00%)	-332.58
NETT AMOUNT	1330.32
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	1020.00
TOTAL SPARE PARTS CHARGES	1350.32
	-----
TOTAL CHARGES	2370.32
ADD 8 % GST	189.63
	-----
GRAND TOTAL	2559.95
	-----