

Surveyor:

Date: 19/06/2023
Vehicle No: SMK5796S
Model: TOYOTA PRIUS PLUS
Chassis: JTDZS3EU70J035790-2018
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SLQ4725J
Date of Accident: 15/06/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$1,000.00	800
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH, REAR BUMPER, SIDE SKIRT RH & ETC.	\$1,000.00	600
LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.	\$120.00	60
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER QUARTER GLASS, REAR FENDER QUARTER GLASS SEALANT & ETC. TO EFFECT REPLACE OF REAR FENDER RH.	\$150.00	50
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.	\$350.00	100
LABOUR CHARGES TO REMOVE & REPLACE REAR RIM RH.	\$120.00	X
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	X
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	60
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00	20

LABOUR TOTAL \$3,020.00

TING AN

TOTAL \$8,388.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Head office

8 Kung Chong Road Singapore 169143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

