

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH6343D
MAKE REG 24.11.2016
MODEL HYU- I40

DATE 18.06.2023

CHIANG /INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER GRILLE IH			\$187.20
1	FRONT BUMPER ASSY			\$1,052.20
10	FRONT BUMPER CLIPS		\$2.20	\$22.00
1	FRT BUMPER TOP BRACKET LH /rh			\$24.60
1	RADIATOR GRILLE			\$1,480.00
1	RADIATOR GRILLE U MOULDING			\$251.00
1	RADIATOR GRILE H EMBLEM			\$129.50
1	FRONT FENDER LH			\$663.00
1	FRONT FENDER SHIELD LH			\$169.30
1	FRONT UNDER COVER			\$334.60
1	BONNET ASSY			\$2,508.80
1	BONNET HINGES LH /RH			\$126.70
1	FRONT FENDER APRON PANEL LH			\$637.00
1	HEADLAMP SUPPORT PANEL			\$907.40
1	HEADLAMP LH			\$1,388.00
1	FRONT DOOR LH			\$2,707.70
1	FRONT TIE ROD LH			\$125.20
1	FRONT STRG BALL JOINT LH			\$73.10
1	FRONT SHOCK ABSORBER LH			\$342.20
1	FRONT SUSPENSION UPPER ARM LH			\$250.40
1	FRONT SUSPENSION LOWER ARM LH			\$595.90
1	KNUCKLE ARM LH			\$552.00
1	WHEEL HUB BEARING LH			\$153.60
	SUB TOTAL			\$14,681.40
	20.00%			\$2,936.28
	DISCOUNTED TOTAL			\$11,745.12
1	FRONT TYRE RH			\$216.00
1	FRONT DOOR COMFORT LOGO STICKER			\$75.00
				\$294.40
	Labour Charge			
	Panel Beating			\$1,100.00
	Spray Painting Charge			\$800.00
	Remove/Refix Front UC Suspension			\$90.00
	Reset Front Wheel Alignment			\$60.00
	Check wiring & Lighting			\$60.00
	TOTAL LABOUR			\$2,110.00
	ESTIMATE TOTAL			\$14,149.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Charge

Panel Beating

Spray Painting Charge

Remove/Refix Front UC Suspension

Reset Front Wheel Alignment

Check wiring & Lighting

Tanghin 97495449 TOTAL LABOUR

19/6/23 2:50pm ESTIMATE TOTAL

C/S Nammy at the car

4 days

Tanghin C/Chandran

- To provide taxi book value
- To check repair limit

Date/Time: 19.06.2023 14:51 Page : 1


am: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 5900807 JC NO305558183

OMER	REGN NO.: SH 6343D	MILEAGE
S COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
OMER NO. 7010045	MODEL I-40	DATE/TIME IN 18.06.2023 17:00
ESS 383 SIN MING DRIVE	YR OF MANU. 24.11.2016	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMHU096479	COMPLETION DATE/TIME:
(R) 65508755 (O)		
(P)		
UNT CARD NO.		

Ident Date: 18.06.2023
TURE: 3P 18.06.2023

JOB DESCRIPTION

NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

: SH 6343D CHIANG

Vehicle No.: SH 6343D

Service Advisor

Signature/Date

Name of Service Advisor

Date

ned to Service Reception upon collection

To be kept by Security Guard