

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHB3645P**
 MAKE **HYUNDAI**
 MODEL **IONIQ**

DATE: **13.06.23**
 MVA **JUMANI**
 DOA: **13.06.23**

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			cut \$459.40
1	REAR BUMPER CENTRE MLDG			de \$451.25
1	REAR BUMPER BEAM			cut \$394.80
1	REAR BUMPER CLIPS			de \$22.00
1	REAR BUMPER TOW COVER			de \$98.80
1	REAR FOG LAMP			cut \$201.50
1	ANTENNA SMARTKEY			cut \$40.60
	REAR BUMPER LOWER CENTRE MOULDING			cut \$155.00
	<i>Sub</i>			
	<i>side cover LH \$108</i>			
	<i>Bumper stay LH \$138.10</i>			
	SUB TOTAL			\$1,823.35
	LESS 20%			\$364.67
	DISCOUNTED TOTAL		<i>2069.45</i>	\$1,458.68
			<i>1655.56</i>	
	REVERSE SENSOR			cut \$180.00 NET
	REAR NUMBER PLATE			cut \$55.00 NET
	REAR BUMPER MAT			cut \$50.00 NET
			<i>2875</i>	
	NET TOTAL			\$285.00
	Labour Charge			
	PANEL BEATING		<i>630</i>	<i>350</i> \$400.00
	SPRAY PAINT			<i>250</i> \$300.00
	REMOVE/REFIX REVERSE SENSOR			<i>3</i> \$50.00
	<i>Transfer 97495749</i>			
	<i>up 13/6/23 05 pm</i>			
	TOTAL LABOUR		<i>2570.50</i>	<i>4592050</i> \$750.00
	<i>2 days</i>			
	<i>1/5 hour diff repair</i>			
	<i>Transfer C (Whan) on</i>			
	ESTIMATE TOTAL		<i>2 days #</i>	\$2,496.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.