

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

21-Jun-23

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8092 B

1 pc	Rear o/s fender inner shield	\$	205.29 X
1 pc	Rear o/s fender	\$	1,525.73 RX
1 pc	Front o/s door	\$	1,723.60 RY
2 pcs	Front o/s door hinges @ \$39.00	\$	78.00 X
1 pc	Rear o/s door	\$	2,017.48 bt
2 pcs	Rear o/s door hinges @ \$39.00	\$	78.00 X
1 pc	Rear bumper	\$	811.11 RX
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 X
1 pc	Rear o/s rim	\$	246.00 cut
		\$	6,789.61
		Less 20%	\$ 1,357.92
		\$	5,431.69

S/NETT

1 set	Rear bumper clips	\$	48.00 X
1 pc	Rear o/s fender sticker	\$	60.00 na
1 set	Rear o/s fender inner shield clips	\$	28.00 X
1 set	o/s door stickers	\$	100.00 na-80
	Sundry	\$	50.00 X
	To check rear o/s wheel alignment	\$	80.00 ✓
	To dismantle and refit reverse sensor into new rear bumper and test system	\$	120.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front o/s door, rear o/s door, rear o/s fender, rear bumper, o/s rocker panel, etc	\$	1,400.00 600
	To putty and spray painting on the rear bumper, rear o/s fender, rear o/s rim, rear o/s door, front o/s door, o/s rocker panel	\$	1,200.00 800
	To apply rustproofing on the repaired and replaced panels	\$	180.00 30
	Total	\$	8,697.69

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taufik 97495789
21/6/23 e 11am
taufik@lkkauto.com.
4 days
1/3 Resurvey after repair.

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHB8092B
 Previous Vehicle No.: -
 Effective Date of Ownership: 08 Mar 2017
 Original Regn Date: 08 Mar 2017
 Registration Date: 08 Mar 2017
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ119097
 Engine No.: D4FBGZ096074
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$21,008.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 07 Mar 2025
 Minimum PARF Benefit: \$8,347.00
 No. of Transfers: 0
 IU Label No.: 1050704410
 COE No.: 2017030801004154D
 COE Expiry Date: 07 Mar 2025
 COE Category: A - Car (up to 1600cc & 97kW (130bhp))
 COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))