

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23006255/Uqy3m4	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 02/08/2023	
			Code	e: AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBN 1886G	Veh. Inspected	SMW 846B	
	Policy No.	P20750818R01	Coverage (\$)	0.00	
	Claim No.	C200222766/KY	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	20/06/2023	
2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN GOLF R-LINE (A)	c.c	1395	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	WVWZZZAUZGW271247	Colour	RED	
	Odometer	160845 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/40R18	MICHELIN	6 mm	
	L/H Front Tyre	225/40R18	MICHELIN	6 mm	
	R/H Rear Tyre	225/40R18	GOODYEAR	6 mm	
	L/H Rear Tyre	225/40R18	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/05/2023	Inspection Date	04/07/2023	
	Survey held at	PRECISE AUTO SERVICE			
		NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a.	ia. Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	,	Estimate Days of Repair			

ESTIMATED NORMAL PERIOD FOR REPAIR:

2 Working Days