

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd
6 Raffles Quay
#22-00
Singapore 048580From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 10 Jul 2023

Preliminary Advice

Vehicle No	: GBL9335M	Accident Date	: 15/06/2023
Make	: NISSAN NV350 URVAN	Policy No.	: D22MFL0008440
Assignment Date	: 20/06/2023	Excess	: S\$400.00
Date of Inspection	: 21/06/2023	Est. Duration of Repair	: 6
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,141.50	(Estimate \$13,072.70 + Supplementary \$5,068.80)
Revised Amount	:S\$	11,994.00	
Check Items (Estimated)	:S\$	2,508.90	
Total	:S\$	14,502.90	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	49,816.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,184.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.