



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL
C/O TAN KOK QUAN PARTNERSHIP
1 WALLICH STREET #07-02 GUOCO SINGAPORE
078881

Ref: CS3/III21003250/Tnp3e2-1

Date: 06/07/2023

Code: III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1614L	Veh. Inspected	FBL 6114D
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	CF.LHP.0256.23	Excess (\$)	0.00
Assign From	JIA YI (TAN KOK QUAN)	Assign Date	21/06/2023

2. Vehicle Particulars & Condition

Make & Model	YAMAHA MT-03	c.c	321
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MH3RH07K000004596	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/60 R17	BRIDGESTONE	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/60 R17	BRIDGESTONE	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2020	Inspection Date	12/03/2021
Survey held at	CADRE AUTOMOBILE 1 KAKI BUKIT AVE 6 #02-49 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**