

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Date: 30th Jun 2023 Your Ref: S2M045GO

Our Ref: CS3/ASM22006229/Dqp3e2-1

## M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard #48-01 Marina Bay Financial Centre Tower 2 Singapore 018983 (The Motor Claims Department)

Attn: Low Garnet

Dear Sir / Madam.

## **EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLR 4375E**

**INSURED VEHICLE: SME 9251C ACCIDENT DATE: 28/06/2022** 

We thank you for your instruction on 21/06/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLR 4375E from M/s Impact Analysis Consulting Pte
- b) Singapore Accident Statement of Vehicles SLR 4375E and SME 9251C.
- c) Final Repair Bill of SLR 4375E from M/s Garage 13 Pte Ltd.
- d) Colour damaged vehicle photographs of SLR 4375E.

Pre-Repair Inspection Date: 30/06/2023 at M/s 8 Kaki Bukit Ave 4, #02-54/55 Premier @ Kaki Bukit, Repairer: Garage 13 Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

: SLR 4375E Registration Number

: Mazda CX-3 XD Touring 1.5 A/T Diesel Turbo Make & Model

: 2017

Year of Registration
Chassis Number Chassis Number : DK5FW131863

**Engine Capacity** : 1498 cc

- 2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.