

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2300238
Date: 21 Jun 2023

Veh Reg No: GR7700P
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5

Chasis No: JN1SC2F24Z0860110
Reg. Date: 29/09/2017
Your Ref No: XE1410H

Claim Type: Third Party
Accident Date: 15/06/2023
TP Veh Reg No: XE1410H

Estimate Repair Cost to Vehicle No :GR7700P

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Net Price		
1	1 PC FRT PANEL	1,738.00	
2	1 PC FRT "CABSTAR" EMBLEM	86.00	
3	1 PC FRT WIPER PANEL	677.00	
4	1 PC HEADLAMP RH	569.80	
5	1 PC HEADLAMP RH LOWER GARNISH	118.00	
6	1 PC HEADLAMP LH	569.80	
7	1 PC HEADLAMP LH LOWER GARNISH	118.00	
8	1 PC FRT FENDER LH	263.80	
9	1 PC FRT BUMPER	1,155.00	
10	2 PCS FRT BUMPER BRACKET	354.80	
11	1 PC FRT LH TOWING HOOK	281.90	
12	1 PC FRT BUMPER INNER CROSSMEMBER	799.20	
13	1 PC FRT CARRIAGE LIFT UP CROSSMEMBER	996.50	
14	2 PCS FRT CARRIAGE LIFT UP MOUNTING	592.20	
15	1 PC FRT BUMPER REINFORCEMENT	366.80	
16	1 PC FRT GRILLE	644.00	
17	1 PC FRT GRILLE EMBLEM	97.00	
18	1 PC FRT LH DOOR LOCK PANEL	2,026.60	
19	1 PC FRT RH DOOR LOCK PANEL	2,026.60	
20	1 PC FRT WINDSCREEN GLASS TOP MOUNTING	169.80	
21	2 PCS FRT WINDSCREEN GLASS SIDE MOUNTING	196.80	
22	1 PC FRT WINDSCREEN GLASS BOTTOM MOUNTING	177.60	
23	1 PC AIRCON DISCHARGE PIPE	396.80	
24	1 PC AIRCON RECEIVER PIPE	292.10	
25	2 PCS AIRCON WATER HOSE	376.80	
26	1 PC FRT DASHBOARD TOP	876.10	
27	1 PC FRT DASHBOARD BOTTOM	714.90	
28	1 PC AIRCON AIR BLOWER	1,060.80	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Estimate No: EST2300238
Date: 21 Jun 2023

Veh Reg No: GR7700P
Make/Model: NISSAN CABSTAR 3.0
 5M/T ABS 2DR 2WD
 EURO 5

Chasis No: JN1SC2F24Z0860110
Reg. Date: 29/09/2017
Your Ref No: XE1410H

Claim Type: Third Party
Accident Date: 15/06/2023
TP Veh Reg No: XE1410H

Estimate Repair Cost to Vehicle No :GR7700P

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29	1 PC AIRCON COOLER COIL ASSY	1,881.50	
30	1 PC FRT EXHAUST CATALYST CONVERTER	2,499.80	
31	1 PC REAR TAIL GATE	1,877.00	
32	3 PCS REAR TAIL GATE HINGE	558.00	
33	1 PC TAIL GATE LOWER PANEL	1,671.40	
34	1 PC TAIL LAMP - RH	266.30	
35	1 PC TAIL LAMP PANEL RH	99.00	
36	1 PC TAIL LAMP LH	266.30	
37	1 PC TAIL LAMP PANEL LH	99.00	
38	1 PC REAR NUMBER PLATE PANEL	212.80	
39	1 PC REAR NUMBER PLATE LAMP	119.00	
40	1 PC TAIL GATE LOCK RH	199.20	
41	2 PCS TAIL GATE STOPPER RUBBER RH	63.60	
42	1 PC TAIL GATE STOPPER RUBBER BRACKET RH	99.60	
43	1 PC REAR TAIL GATE HANDLE RH	202.60	
44	1 PC REAR TAIL GATE LOCK LH	199.20	
45	2 PCS REAR TAIL GATE STOPPER RUBBER LH	63.60	
46	1 PC TAIL GATE STOPPER RUBBER BRACKET LH	99.60	
47	1 PC REAR CARRIAGE FLOOR PANEL	4,819.40	
48	1 PC SPARE TYRE LOCK	399.70	
		33,439.30	
		Less 10%	3,343.93
			30,095.37
	Special Net		
49	1 PC FRT NUMBER PLATE	50.00	
50	1 SET FRT GRILLE CLIPS	40.00	
51	1 PC FRT WINDSCREEN SEAL	60.00	
52	1 PC FRT WINDSCREEN SEALANT	60.00	
53	1 PC REAR TAIL GATE 'NISSAN' STICKER	91.00	
54	1 PC REAR TAIL GATE "6 PAX" STICKER	30.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Estimate No: EST2300238
Date: 21 Jun 2023

Veh Reg No: GR7700P
Make/Model: NISSAN CABSTAR 3.0
 5M/T ABS 2DR 2WD
 EURO 5

Chasis No: JN1SC2F24Z0860110
Reg. Date: 29/09/2017
Your Ref No: XE1410H

Claim Type: Third Party
Accident Date: 15/06/2023
TP Veh Reg No: XE1410H

Estimate Repair Cost to Vehicle No :GR7700P

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
55	1 PC REAR TAIL GATE "70KM/H" STICKER	30.00	
56	1 PC TAIL GATE ALUMINIUM PANEL	850.00	
57	1 SET REVERSE SENSORS	250.00	
58	1 PC REAR NUMBER PLATE	50.00	
59	1 PC REAR CARRIAGE FLOOR ALUMINIUM PANEL	1,500.00	
60	1 PC REAR CARRIAGE SIDE GATE ALUMINIUM PANEL RH	1,000.00	
		<u>4,011.00</u>	4,011.00
	Labour		
61	1 TO CHECK WIRING (FRONT)	50.00	
62	1 TO REMOVE AND REFIT FRONT WINDSCREEN	120.00	
63	1 TO REMOVE AND REFIT SEAT CUSHION	300.00	
64	1 TO REMOVE AND REFIT DASHBOARD	500.00	
65	1 TO REMOVE AND REPLACE AIR CON BLOWER / COOLING COIL ASSY	400.00	
66	1 TO REMOVE AND REFIT FRONT CABIN	1,000.00	
67	1 TO REFILL AIRCON GAS	120.00	
68	1 TO SPRAY UNDERSEAL	150.00	
69	1 (FRONT) TO SPRAY PAINTING	1,500.00	
70	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,200.00	
71	1 TO CHECK WIRING (REAR)	50.00	
72	1 TO REMOVE AND REFIT 4PCS ALUMINIUM PANEL	1,000.00	
73	1 TO REMOVE AND REFIT REAR CARRIAGE ROOF TOP	600.00	
74	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
75	1 TO REMOVE AND REFIT REAR CARRIAGE	1,200.00	
76	1 TO REPLACE STICKERS	80.00	
77	1 TO SPRAY UNDERSEAL	150.00	
78	1 (REAR) TO SPRAY PAINTING	2,000.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 15/06/2023
TP Veh Reg No: XE1410H

Estimate No: EST2300238

Date: 21 Jun 2023

Veh Reg No: **GR7700P**
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5

Chasis No: JN1SC2F24Z0860110

Reg. Date: 29/09/2017

Your Ref No: XE1410H

Estimate Repair Cost to Vehicle No :GR7700P

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
79	1	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	3,000.00
		14,500.00	14,500.00
		Total	S\$ 48,606.37
		Add GST @ 8%	3,888.51
		Total Amount Payable	<u>S\$ 52,494.88</u>

TOTAL: SINGAPORE DOLLAR FIFTY TWO THOUSAND FOUR HUNDRED NINETY FOUR AND CENTS EIGHTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE