



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23006374/Kny3m4 Date: 04/08/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 5904U	Veh. Inspected	SLL 1922C
Policy No.	D-23100887MFBP	Coverage (\$)	0.00
Claim No.	D23002166MFBP	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	23/06/2023
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES E200 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2130422A052363	Colour	METALLIC GREY
Odometer	105688 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	BRIDGESTONE	8 mm
L/H Front Tyre	225/55 R17	BRIDGESTONE	8 mm
R/H Rear Tyre	225/55 R17	BRIDGESTONE	8 mm
L/H Rear Tyre	225/55 R17	BRIDGESTONE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/06/2023	Inspection Date	26/06/2023
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	