



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS/CTI23006378/Kqp3e2	
			Date: 18/07/2023	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBE 9863S	Veh. Inspected	GBJ 236K
	Policy No.	DMCVSNW00037092307	Coverage (\$)	0.00
	Claim No.	SNM23D204345	Excess (\$)	0.00
	Assign From	ALFRED TOH	Assign Date	23/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	RENAULT KANGOO (A)	c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	VF1FWT8H361486551	Colour	WHITE
	Odometer	46485 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DAVANTI	6 mm
	L/H Front Tyre	195/65 R15	DAVANTI	6 mm
	R/H Rear Tyre	195/65 R15	DAVANTI	7 mm
	L/H Rear Tyre	195/65 R15	DAVANTI	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	19/06/2023	Inspection Date	23/06/2023
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	