

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23006382/Uvy3m4	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	12/07/2023	
			Code	: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMS 9678G	Veh. Inspected	SNA 749C	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10023024 /CH	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	23/06/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MAZDA3 HATCHBACK SP (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	JM6BM44A8G0323798	Colour	BLUE	
	Odometer	122821 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	GOODYEAR	6 mm	
	L/H Front Tyre	205/60 R16	GOODYEAR	6 mm	
	R/H Rear Tyre	205/60 R16	GOODYEAR	6 mm	
	L/H Rear Tyre	205/60 R16	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/06/2023	Inspection Date	26/06/2023	
	Survey held at	LEANG AUTOMOTIVE			
		BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

9 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: