



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2304176

64 CECIL STREET  
#05-02 IOB BUILDING  
SINGAPORE 049711

INV Date 03/07/2023  
Reference CS3/III23003039/Dvy3e2-1  
Code III2

### PROFESSIONAL SERVICE FEE

Vehicle No. SJR 2629K  
Insured Veh. SLK 3765G  
Claim No. MFL2023D0003159  
Policy No. D21MFL0000447\_02  
Accident Date 19/03/2023  
Inspection Date 27/03/2023

| Description                                                      | Total         |
|------------------------------------------------------------------|---------------|
| Survey Inspection                                                | 250.00        |
| Resurvey Inspection                                              |               |
| Digital Photographs                                              |               |
| Transportation                                                   |               |
| Less: Pre-Repair Survey Fee (Invoice.AC2302265 dated 13/04/2023) | -120.00       |
| <b>Subtotal</b>                                                  | <b>130.00</b> |
| <b>GST (8%)</b>                                                  | <b>10.40</b>  |
| <b>Grand Total</b>                                               | <b>140.40</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**KHM**