

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMC8760S
Chassis No : JHMRU1830GX204016
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHONG KIM HWA
Ins Policy No :
Date of Accident : 22/6/2023

Document No. : SQT23001903 Page 1
Date : 24. Jun 2023
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B4534021
Date | Time : 24. Jun 2023 10:35:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHONG KIM HWA OWNER INSURER: FWD ACC DATE: 22/06/2023 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL TP VEH: SG5075P						
60260-T7A-J00ZZ	PANEL COMPL.FR.FENDER <i>bt</i>	1	422.70	25	317.02	25.36	342.38
74157-T7A-J01ZC	PROTECTOR,L.FR.WHEEL ARCH <i>sen</i>	1	164.40	25	123.30	9.86	133.16
74150-T7A-N00	FENDER ASSYL.FR.INNER <i>X</i>	1	99.10	25	74.32	5.95	80.27
91501-TR0-003	CLIP,INNER FENDER <i>de</i>	11	2.80	25	23.10	1.85	24.95
04711-T7A-N00ZZ	FACE,FR.BUMPER	1	524.30	25	393.22	31.46	424.68
04712-T7A-900ZZ	FACE,FR.BUMPER LOWER <i>sc</i>	1	255.30	25	191.47	15.32	206.79
71190-T7A-000	BEAML.FR.BUMPER UPPER <i>?</i>	1	28.40	25	21.30	1.70	23.00
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE <i>u</i>	1	11.80	25	8.85	0.71	9.56
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE <i>u</i>	1	11.80	25	8.85	0.71	9.56
91505-TM8-003	CLIP,BUMPER <i>u</i>	22	2.30	25	37.95	3.04	40.99
33100-T7S-E11	HEADLIGHT ASSY,R. <i>X</i>	1	1974.40	25	1480.80	118.46	1599.26
33150-T7S-E11	HEAD LIGHT ASSY,L. <i>?</i>	1	1974.40	25	1480.80	118.46	1599.26
60400-T7A-901ZZ	BULKHEAD COMP,FR. <i>X</i>	1	465.00	25	348.75	27.90	376.65
42700-T7A-J92	DISK,ALUMINIUM WHEEL <i>sc</i>	1	836.20	25	627.15	50.17	677.32
44306-T7A-N00	DRIVESHAFT ASSYL. <i>?</i>	1	1150.90	25	863.17	69.05	932.22
01463-T2G-A01	CALIPER SET,FR. <i>?</i>	1	46.80	25	35.10	2.81	37.91
44300-T6A-J51	BEARING ASSYFR.HUB <i>?</i>	1	147.90	25	110.92	8.87	119.79
44600-T0B-A00	HUB ASSYFR. <i>?</i>	1	200.40	25	150.30	12.02	162.32
45251-TA0-A02	DISKFR.BRAKE <i>?</i>	1	212.20	25	159.15	12.73	171.88

Printed on 24/6/2023 1:18:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMC8760S
Chassis No : JHMRU1830GX204016
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHONG KIM HWA
Ins Policy No :
Date of Accident : 22/6/2023

Document No. : SQT23001903 Page 2
Date : 24. Jun 2023
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B4534021
Date | Time : 24. Jun 2023 10:35:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
45255-T7A-000	GUARDFR.BRAKE SPLASH ?	1	29.90	25	22.42	1.79	24.21
45022-T4N-H02	PAD SET,FR. ?	1	242.00	25	181.50	14.52	196.02
51216-T7A-000	KNUCKLEL.FR. ?	1	260.70	25	195.52	15.64	211.16
51220-STK-A01	JOINTFR.LOWER BALL ?	1	107.80	25	80.85	6.47	87.32
51306-T7A-004	BUSHR.FR.STABILIZER HOLDER ?	1	8.30	25	6.22	0.50	6.72
51325-T7A-003	LINK COMPL.FR.STABILIZER ?	1	51.20	25	38.40	3.07	41.47
51360-T7J-H11	ARM ASSYL.FR.LOWER ?	1	262.50	25	196.87	15.75	212.62
57455-T7A-003	SENSOR ASSYL FR ?	1	40.40	25	30.30	2.42	32.72
51621-T7M-H02	ABSORBER UNITL.FR.SHOCK ?	1	324.70	25	243.52	19.48	263.00
51401-T7A-J12	SPRINGFR. ?	1	99.10	25	74.32	5.95	80.27
51722-T7A-013	RUBBERFR.BUMP STOPPER ?	1	23.90	25	17.92	1.43	19.35
51694-TX6-A01	RUBBERL.FR.SPRING LOWER ?	1	15.50	25	11.62	0.93	12.55
50200-T7A-023	SUB FRAME COMPFR.SUSPENSION ?	1	807.90	25	605.92	48.47	654.39
50275-T5E-000	STAYR.RR.SUB FRAME ?	1	12.70	25	9.52	0.76	10.28
50276-T5E-000	STAYL.RR.SUB FRAME ?	1	15.50	25	11.62	0.93	12.55
53211-T7A-N01	COLUMN COMPSTEERING ?	1	2441.50	25	1831.12	146.49	1977.61
53213-T7A-N01	SHAFT COMPSTRG INTER MEDIATE ?	1	249.00	25	186.75	14.94	201.69
53320-T5A-000	COVERSTEERING JOINT ?	1	3.80	25	2.85	0.23	3.08
77901-T5A-J80	SUB CORDCABLE REEL ?	1	55.70	25	41.77	3.34	45.11
35000-T0A-003	SENSOR ASSYSTREERING ?	1	244.40	25	183.30	14.66	197.96
77900-T5A-J22	REEL ASSY,CABLE ?	1	292.60	25	219.45	17.56	237.01
77960-T7S-Z81	SRS UNIT ?	1	806.70	25	605.02	48.40	653.42
77970-T6A-J11	SENSOR ASSYSIDE IMPACT ?	2	140.90	25	211.35	16.91	228.26
Sum Item					11463.65	917.07	12,380.72
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00		280.00	22.40	302.40
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	580.00		580.00	46.40	626.40
BMS00R	RENEW ECU & ERASE ENGINE WARNING LIGHT	1	650.00		650.00	52.00	702.00

Printed on 24/6/2023 1:18:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838
Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SMC8760S
Chassis No : JHMRU1830GX204016
Model : HRV LX-SIN CVT YM 2016
Owner's Name : CHONG KIM HWA
Ins Policy No. :
Date of Accident : 22/6/2023

Document No. : SQT23001903 Page 3
Date : 24. Jun 2023
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B4534021
Date | Time : 24. Jun 2023 10:35:35 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BPBODY	TOWING ACC SCENE AUTHORISE WORKSHOP FOR REPORTING	1	120.00		120.00	9.60	129.60
BPBODY	TOWING FROM AUTHORISE WORKSHOP TO KAH MOTOR	1	120.00		120.00	9.60	129.60
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)1	1	1625.00		1625.00	130.00	1755.00
BPBODY	REPLACE STEERING COLUMN ASSY	1	1300.00		1300.00	104.00	1404.00
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	3250.00		3250.00	260.00	3510.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	4160.00		4160.00	332.80	4492.80
Sum Labor					12185.00	974.80	13,159.80

Survey By : *[Signature]*
Date & Time : 26/06/23 @ 1545 9 days
Excess :
Status :
Signature : *[Signature]* *Key key by paint*

Total Amount 23,648.65 1,891.87 25,540.52
Total (Inclusive of GST) 25,540.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 24/6/2023 1:18:49 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	947Z
Vehicle No.:	SMC8760S
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jun 2023
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	L15B4534021
Chassis No.:	JHMRU1830GX204016
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,245.00
Original Registration Date:	26 Jul 2018
First Registration Date:	26 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$21,743.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jul 2028
PARF Rebate Amount:	\$16,307.00
COE Expiry Date:	25 Jul 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,000.00
COE Rebate Amount:	\$12,674.00
Total Rebate Amount:	\$28,981.00

The information contained herein is correct as at 29 Jun 2023

OK

Honda HR-V 1.5A LX

\$81,800 Instalment \$1,129/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator

sgcormart

SAVE UP TO **\$600**
ON YOUR CAR INSURANCE RENEWAL!

> Get Quotes Now

Overview Financial Photo Research

Depreciation	<i>i</i> \$14,550 / year
Reg. Date	16-May-2018 (4yrs 10mths 16days COE left)
Manufactured	<i>i</i> 2017
Mileage	-
Transmission	Auto
Engine Cap	1,496 cc
Road Tax	<i>i</i> \$682 / year
Power	96.0 kW (128 bhp) View specs of the Honda HR-V (2015-2021)
Curb Weight	<i>i</i> 1,190 kg
COE	<i>i</i> \$37,000
OMV	<i>i</i> \$21,077
ARF	<i>i</i> \$21,508
Dereg Value	<i>i</i> \$33,120 as of today
No. of Owners	<i>i</i> 2