



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23006418/Uny3e2	
			Date: 11/07/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SFF 1143L	Veh. Inspected	SMY 4652G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2302531/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	26/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH HYBRID (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	ZWR800432656	Colour	BLACK
	Odometer	77932 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40Z R18	DUNLOP	7 mm
	L/H Front Tyre	225/40Z R18	DUNLOP	7 mm
	R/H Rear Tyre	225/40Z R18	DUNLOP	7 mm
	L/H Rear Tyre	225/40Z R18	DUNLOP	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/06/2023	Inspection Date	27/06/2023
	Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	