

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19-	-9607198-R	
		Affiliated to Federation Internation	nale Des Experts En Au	tomobile	
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI23006421/Uny3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 11/07/2023	
			Co	ode: AGI	
1.		Policy Particulars	:- THIRD PARTY CI	LAIM	
	Insured Veh.	SLB 1176S	Veh. Inspected	SLP 4257Z	
	Policy No.	P10804001R00	Coverage (\$)	0.00	
	Claim No.	C10023075/JT	Excess (\$)	0.00	
	Assign From	DON BONG	Assign Date	26/06/2023	
2.		Vehicle Partic	culars & Condition		
	Make & Model	MITSUBISHI LANCER EX (A)	c.c	1590	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JMYSRCY1AGU006802	Colour	BLUE	
	Odometer	141217 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	TOURADOR	7 mm	
	L/H Front Tyre	205/60 R16	TOURADOR	7 mm	
	R/H Rear Tyre	205/60 R16	TOURADOR	7 mm	
	L/H Rear Tyre	205/60 R16	TOURADOR	7 mm	
4.	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE D	ETAILS.			
5.	General Information				
	Accident Date	26/06/2023	Inspection Date	27/06/2023	
	Survey held at	LEE BROTHERS AUTOMOTIVE	PTE LTD		
		1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)III / IOOO IIDAIII	Estimate Days of Repair			
			•		

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: