



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC23000692/Tvy3e2-1	
			Date: 28/06/2023	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	XD 7262J	Veh. Inspected	SMG 8080A
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/026859	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	26/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ E200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD2120342A859387	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/40 R18	WEST LAKE	6 mm
	L/H Front Tyre	245/40 R18	WEST LAKE	6 mm
	R/H Rear Tyre	245/40 R18	WEST LAKE	6 mm
	L/H Rear Tyre	245/40 R18	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	17/01/2023	Inspection Date	20/01/2023
	Survey held at	GOODFELLAS AUTO SERVICE CENTRE PTE LTD 7 SOON LEE STREET, #01-37, ISPACE, SINGAPORE 627608		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	