



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23006465/Uvy3e2 Date: 06/07/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLE 4576K	Veh. Inspected	SMK 2660U	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/1127	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	27/06/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA JAZZ (A)	c.c	1318	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JHMGK3850KS212601	Colour	MAROON	
Odometer	89128 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	DUNLOP	7 mm	
L/H Front Tyre	175/65 R15	DUNLOP	7 mm	
R/H Rear Tyre	175/65 R15	DUNLOP	7 mm	
L/H Rear Tyre	175/65 R15	DUNLOP	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	18/06/2023	Inspection Date	27/06/2023	
Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 02 APR 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	