



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: EILEEN LEE			Ref: CS3/INC23000975/Tvp3m4-1 Date: 30/06/2023 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLG 7673H	Veh. Inspected	SNC 819Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1206885-002	Excess (\$)	0.00
	Assign From		Assign Date	21/06/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	ZWR800504928	Colour	SILVER
	Odometer	96619 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65R15	DAVANTI	6 mm
	L/H Front Tyre	195/65R15	DAVANTI	6 mm
	R/H Rear Tyre	195/65R15	DAVANTI	6 mm
	L/H Rear Tyre	195/65R15	DAVANTI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/01/2023	Inspection Date	31/01/2023
	Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	