

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC23006499/Tny3e2	
	300 BEACH ROAD			Date:	06/07/2023	
	#17-04/07 THE CO	NCOURSESINGAPORE 199555		On also	I DCO	
4		Dell'es Deut'estess	(TIUDD DADT	Code:		
1.	,					
	Insured Veh.	SKZ 939A	Veh. Inspected	<u> </u>	SLB 7161U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VP05/027601	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		27/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MR053REH104547888	Colour		WHITE	
	Odometer	158320 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	TRIANGLE		6 mm	
	L/H Front Tyre	205/55 R16	TRIANGLE		6 mm	
	R/H Rear Tyre	205/55 R16	TRIANGLE		6 mm	
	L/H Rear Tyre	205/55 R16	TRIANGLE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DI	ES SEE DETAILS.				
5.	General Information					
	Accident Date	23/06/2023	Inspect Date /	Time	04/07/2023 (10:30 AM)	
	Survey held at	ECLIPSE AUTO PTE LTD				
		155 KAKI BUKIT AVENUE 1 #01□00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23006499/Tny3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

M.MATAI, AMSAE-A
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.